

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page 8440)

A hemlock, 6" dia., for 1/4 sec. cor., mkd: 1/4 S20 on W and 21 on E sides; from which

A hemlock, 16" dia., bears S.52°E., 3 lks., mkd: 1/4 S21 BT.

A fir, 28" dia., bears N.9°W., 32 lks., mkd: 1/4 S20 BT.

F.L. Hart's house, bears N.88°W., 24 chs.

A.B. Hart's house, bears N.78°W., 25 chs.

Douglas Co. Surveyors Office - George J. Wenderoth, Deputy - 1945 or 1946 - C.S. 38/41A & Old system Corner renewal #6

Corner renewal #6 (old system, no other record)

Found old BT 24" fir N.9°W., 21.2 ft. dead

Drive 5/8" bolt for corner.

Scribe: A 36" fir N.75°E., 50.2 ft.

A 40" Fir N.25°04'W., 54.4 ft.

C.S. File 38/41A notes

Found 36" Fir N.55°E., 40.2 lying on ground. Stone & other tree gone.

Drive 5/8" iron bolt for corner.

Mark: 36" Fir N.75°E., 50.2 ft.

40" Fir N.25°04'W., 54.4 ft.

C.S. File 38/41A map

5/8" I. Bolt

36" Fir N.75°E., 50.2 ft.

40" Fir N.25°04'W., 54.4 ft.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1969 - C.S. File 54/91-60

Found - No trace of 5/8" Bolt set by Wenderoth, 1946,
Orig. 28" D.Fir, now windfall, N.9°W. 21.1 ft.,
shows brunt scribing

40" D.Fir, now 42" Stump, N.25°W. 54.4 ft., shows scribing.

NE BT was taken out in skid road.

Set - Brass Cap at Cor. mkd: County Surveyors T32S R3W
Office, 1969 1/4 S 20 | S 21

New BTs- 6" D.Fir N.36°W., 46.6 ft. mkd: "1/4 S20 CS BT"

6" Hemlock S15°E., 40.6 ft. mkd: "1/4 S21 CS BT"

This 1/4 corner lies in logging unit about 100 ft. S. of small creek.