

PRIMARY CORNER DESCRIPTION 1/16 80 for Secs. 21 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Glenn Baughman - For: USFS - 8/1974 - M49-69 & C.S. 55/357-12

Set - A 36" long, 2½" galvanized iron pipe 30" in the ground,
in a mound of stones, with a 4" brass cap marked:

1/16

S 21 | S 22

80

RLS 536 1974

BTs- A D.Fir, 18" dia. bears N.25°W., 65.5 ft scribed 1/16
80 S 21 (BT) with a brass washer stamped RLS 536

A D.Fir, 20" dia. bears N.13°E., 43.8 ft scribed 1/16
80 S 22 (BT) with a brass washer stamped RLS 536

Leonard Herzstein, USFS - Jim Landrum & Jim Hamilton - May 4,
1982 - C.S. 61/32-15

Found - 2½" IP with 1974 brass cap properly mkd. firmly set
projecting 2" above ground, leaning slightly
east. (M 49-69)

20" D.Fir stump, N.13°E., 42.9 ft. (Rec. 43.8 ft.)
with scribe marks "1/16 80 S22 BT" and brass
washer stamped "RLS 536" visible on partly healed
double blaze.

A roothole, N.25°W., 60.7 ft. (Rec. 65.5 ft.) with
18" D.Fir stump alongside with scribe marks "1/16
80 S21" and brass washer visible on partly healed
double blaze.

New BTs- 5" chinquapin, N.26¾°E., 38.7 ft. marked "1/16 80
S22 CS BT" on double blaze.

9" chinquapin, S.13¾°W., 45.8 ft. mkd. "1/16 80 S21
CS BT" on double blaze.

Reset ft. steel fence post 3 ft. south with USFS
signs #54-2 and #54-9 attached.

Corner is in USFS clearcut about 80 ft. east of USFS Rd.
#3240.