

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8367)

Set ¼ sec. post, from which
 A Fir, 6" dia., bears N.60°E., 5 lks.
 A Fir, 5" dia., bears N.70°W., 13 lks.

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8406)

The ¼ sec. cor. which is a badly decayed post, marked as described by the Surveyor General. The East BT is uprooted. No trace of the West BT can be found. I destroy this cor. and reestablish it in the same place as follows:
Set a granite stone 20x15x12", 15" in the ground for ¼ sec. cor. mkd. ¼ on West face, from which
 A fir, 40" dia., bears N.25°E., 67 lks., mkd: ¼ S15 BT.
 A fir, 48" dia., bears N.30°W., 13 lks., mkd: ¼ S16 BT.

Douglas Co. Surveyors Office - Ben B. Irving, Co. Surveyor - Jan 1945 - C.S. File 38/41

Granite stone set for corner as orig. 20x15x12" 15" in the ground.
Found original BT as follows:
 40" Fir N.25°E., 67 lks., remarked in bark.
 48" Fir N.30°W., 13 lks., scribe marks not legible.
Marked new BT as follows:
 38" Fir S.77°W., 92 lks. ¼ S16 CS BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1969 - C.S. File 54/91-61

Found - Corner Stone, 20x15x12, in place and mkd.
 Orig. 40", now 50" D.Fir Snag, N.25°E. 44.2 ft., shows scribing.
 Orig. 48", now 48" D.Fir Stob, N.30°W. 8.6 ft., shows brunt axe face no scribing.
 38", now 40" D.Fir Stump, S.77°W. 60.7 ft., shows good bark scribing.
Set Brass Cap at Cor. mkd: County Surveyors Office, 1969 T32S R3W ¼ S16|S 15
New BTs- 6" D.Fir S.83°E. 46.7 ft. mkd: "¼ S15 CS BT".
 5" Hemlock N.50°W. 12.3 ft. mkd "¼ S16 CS BT".
This corner lies about 70 ft. south of ravine.