

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 22 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Glenn Baughman - For: USFS - July 18, 1974 - Tiller Land Survey #13, Contract #004346N - M49-69 & C.S. 55/357

Set - 36" long, 2½" gal. I.P. 32" in the ground, in a mound of stones, with a 4" Brass cap mkd: ¼ S 22

T32S R3W

RLS 536 1974

BTs - A 15" Cedar, bears S.77°W., 10.3 ft., scribed ¼ S22 (BT) with a brass washer stamped RLS 536

A 26" D.Fir, bears S.35°E., 63.6 ft. scribed ¼ S22 (BT) with a "brass washer stamped RLS 536.

Corner lies on gradual Southwest slope, approx. 200 ft. Northeast of creek.

Note - This corner was destroyed in 1913 by Fred Mensch under GLO Group. #14. Surveyor General Record states "I reestablished this corner in its orig. position for Section 15 only as follows: Set a basalt stone, 15x10x5" 10" in the ground, for 1/4 Sec. Cor. for Sec. 15 only, mkd. ¼ on North face: from which a Fir, 24" bears N.37 E., 25 lks. mkd. ¼ S15 BT. A Fir, 20", bears N.30 W. , 37 lks. mkd. ¼ S15 BT. I destroy the marks on the bearing tree south of line.