

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T31-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7688)

-----  
Set ¼ sec. post, from which  
A Laurel 7" dia., bears N.30°E., 26 lks. dist.  
A Pine 8" dia., bears S.5°W., 9 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7733)

-----  
The ¼ sec. cor. which is a post, greatly decayed, marked ¼ S on N. face, I find the 2 bearing trees. I remove this post and set a post, 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on N. face; from which  
A Laurel 7" dia., bears N.30°E., 26 lks. dist. mkd. ¼ S BT  
A Pine 8" dia., bears S.5°W., 9 lks. dist. mkd. ¼ S BT.

George J. Wenderoth, Deputy Co. Surveyor - Wit: Frank Loso - June 1950 - C.S. File 45/229

-----  
Set halfway between sec. corners.  
Set a 1" I.Pipe for the corner, from which  
A 12" Fir bearing N.39°40'E., 18.9 ft.  
A 10" Fir bearing S.71°24'E., 12.3 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan/Feb. 1966 - C.S. File 52/63-69

-----  
Found - Iron pipe at ¼ corner.  
12" Fir, now dead, N.39½°E., 18.9 ft. scribe visible "¼".  
10" Fir now blow down, S.71¼°E., 12.3 ft.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R  
¼ S 34 3  
S 3 W  
T 32 S  
1966  
New BTs- 18" D.Fir N.28°W., 23.0 ft. scribed ¼ S34 CS BT.  
7" W.Fir S.71½°W., 18.8 ft. scribed ¼ S3 CS BT.

Leonard Herzstein, U.S.F.S. (Deputized by DCSO) - Wit: Jim Hamilton - Nov. 24, 1981 - C.S. File 61/29-34

-----  
CONDITION REPORT ONLY  
(Cont. Next Page)

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T31-3

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Found - 1 1/4" I.P., firmly set, projecting 8" above ground with properly mkd. brass cap, with 1 1/2" I.P. alongside.  
12" Fir now a root hole, bears N.39 1/2°E., 18.9 ft. (Rec. N.39°40'E.) with 12" D.Fir log alongside with fragmentary scribe marks visible on partly healed double blaze.  
10" Fir now a root hole bears S.71 1/2°E., 12.3 ft. (Rec. S.71°24'E.) with rotten log alongside with no marks visible.  
18" D.Fir now 18" D.Fir bears N.28°W., 23.8 ft. with healed double blaze.  
7" W.Fir now 9" W.Fir bears S.71 1/2°W., 18.8 ft. with healed double blaze.

Survey by James Artman, RLS #2268 - Dec. 1990 - C.S. File 63/124-4

-----  
Found - 1" Iron pipe with 2 1/2" brass cap, 10" above ground, properly marked.  
Root hole N.39 1/2°E., 18.6 ft., 12" D.Fir, down and rotted.  
Root hole S.71 1/2°E., 12.3 ft., 10" D.Fir, down and rotted.  
20" D.Fir N.28°W., 23.8 ft., healed blazes.  
10" W.Fir S.71 1/2°W., 18.8 ft., dead, healed blazes.  
1 1/2" Iron pipe alongside brass capped pipe.  
New BT - 8" W.Fir S.21°W., 13.9 ft. scribed "1/4 S3 BT" nailed alum. washer mkd. "Artman RLS 2268" flush to BT face.