

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8363)</p> <p>-----</p> <p>Set post, cor. to secs. 10, 11, 14, & 15, from which</p> <ul style="list-style-type: none">A fir, 8" dia., bears N.30°E., 5 lks.A S.Pine, 60" dia., bears S.25°E., 32 lks.A fir, 10" dia., bears S.60°W., 25 lks.A fir, 8" dia., bears N.80°W., 8 lks.
<p>GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8400-1)</p> <p>-----</p> <p>The cor. of secs. 10, 11, 14, & 15 is a badly decayed post, marked & witnessed as described by the Surveyor General. I now destroy this cor. and reestablish it in the same place as follows:</p> <p>Set a granite stone 18x16x4", 12" in the ground for cor. of secs. 10, 11, 14, & 15 mkd with 4 notches on South & 2 notches on East edge, from which</p> <ul style="list-style-type: none">A fir, 12" dia. bears N.41°E., 25 lks mkd: T32S R3W S11 BTA fir, 60" dia. bears S.65°E., 61 lks mkd: T32S R3W S14 BTA fir, 16" dia. bears S.70°W., 16 lks mkd: T32S R3W S15 BTA fir, 9" dia. bears N.14°W., 21 lks. mkd: T32S R3W S10 BT
<p>Douglas Co. Surveyors Office - A.R. Evans, Deputy - Ray G. Irving, J.I Clinton, & Gordon Foster, crew - Feb. 1951 - M8-2, C.S. File 44/92 & Vol. 5 Pg. 39</p> <p>-----</p> <p>Found - A granite rock with cross, from which</p> <ul style="list-style-type: none">An 80" Fir bears S.65°E., 36.8 ft. (No previous record)Cut into a 16" Fir, S 60°W., 10.2 ft. Marked S15 T32S R3W - (The tree rings indicated that this tree was scribed 80 years. ago.) <p>Blazed and scribed new bearing trees.</p> <ul style="list-style-type: none">24" Fir, N.50°E., 18.2 ft. Mkd T32S R3W S11 CSBT16" Fir, N 55°W., 67.4 ft., Mkd T32S R3W S10 CSBT14" Fir, S.85°W., 34.9 Ft. Mkd T32S R3W S15 CSBT.
<p>Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - July 31, 1969 - C.S. File 54/91-37</p> <p>-----</p> <p>Found - Orig. 12", now 16" D.Fir, N.40°E., 16.5 ft shows good scar.</p> <ul style="list-style-type: none">Orig. 9", now 12" D.Fir, N.14°W. 13.9 ft shows good scar. <p>continued next page</p>

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Orig. 16", now 24" D.Fir, S.70°W., 10.6 ft. prev.
opened, scribe visible.
SE BT down
1951 BTs
24", now 29" Fir N.50°E. ~~12.2~~ * 18.2 ft bark scribed
14, D.Fir S.85°W. 34.9 ft shows pitched over scribe
NW bearing tree stump.
Found stone out of place, with "+" near corner.
Set brass cap at Cor. Mkd: COUNTY SURVEYORS T32S R3W
OFFICE S 10|S 11
1969 S 15|S 14
New BT - 14" Laurel S.4°E. 24.0 ft. mkd: T32S R3W S14 CS BT
* Originally typed as 12.2 ft but actual renewal notes show
the distance to be 18.2 ft. 7/7/2011 JC DCSO

Leonard Herzstein, USFS & Deputy Doug. Co. Surveyor -
Witness: Jim Landrum - Nov. 19, 1981 - C.S. 61/29-27

CORNER REPORT ONLY
Found - 1969 County brass cap properly mkd., firmly set,
projecting 18" above ground.
Orig. corner stone is set alongside with "+" on
north side and 4 lines mkd. on top.
1912 GLO, 16" D.Fir bears N.40°E., 16.5 ft. with
healed double blaze.
1912, A roothole, bears S.65°E., 36.8 ft. with 60"
D.Fir log alongside with bark blaze face down.
1912, A 24" D.Fir bears S.70°W., 10.6 ft. with
fragmentary scribe marks visible on previously
opened double blaze.
1912, A 12" D.Fir bears N.14°W., 13.9 ft. with
healed blaze.
A 29" D.Fir bears N.50°E., 18.2 ft. (Rec. 12.2* ft.
see note in 1969 renewal) with scribe marks "T32S
R3W S11 CS BT" visible on bark blaze. 1951
A 14" D.Fir S.85°W., 34.9 ft. with healed double
blaze. 1951
A 14" madrone bears S.4°E., 24.0 ft. with scribe
marks "T32S R3W S14 CS" visible on partly healed
double blaze. 1969
Note - Corner is at NE corner of USFS clear-cut and about
350 ft. north of end of USFS Rd. #3242-S