

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8416)

Set a serpentine stone 15x10x6", 10" in the ground for ¼ sec. cor. mkd. ¼ on North face, from which
A fir, 36" dia., bears N.70°E., 16 lks., mkd: ¼ S26 BT.
A fir, 36" dia., bears S.18°W., 6 lks., mkd: ¼ S35 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1969 - C.S. File 54/91-63

Found - 15x12x6" corner stone mkd. "¼" on North face.
Orig. 36" now 38" D.Fir, N.70°E., 10.6 ft., shows good scar.
Orig. 36" now 38" D.Fir, S.18°W. 4.0 ft. shows good scar.

Set brass cap at ¼ corner mkd: County Surveyors T32S R3W
Office Doug. Co. S 26
1969 Jack. Co. ¼ S 35

All bearing trees O.K. and tagged.

Jackson Co. Surveyors Office - Edward McGinty, Co. Surveyor - R Frost & S Beecher, Techs - Oct. 24, 1988 - C.S. 63/82-5

Found - Projecting 15", the 1" dia. galvanized iron pipe, with 2½" dia. brass cap (properly) mkd.
The orig. 14x11x5" stone, mkd. "¼" as recorded by F. Mensch in 1913, is fd. deposited alongside the above described corner monument.

Corner lies in area of recent forest fire & no trees are available, within a reasonable distance, for references.

The orig. BTs, were felled (high stumped), prior to the fire. Mound stones around corner & in the top center of found charred stumps set pk. nail through bearing tree tag:

1. 32" dia. fir stump, brs. N.70°E., 11.25 ft. to center. Record; 10.56 ft.
2. 34" dia. fir stump, brs. S.20°W., 3.92 ft. to center. Record; S.18°W., 3.96 ft.

Corner lies on (40%) Northwest slope, 64 ft. South of creek, c. N.80°W. & an estimated 500 ft., N.10°W. of small landing alongside road (curve around ridge) c. Southeast & Southwest.

continued next page

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey and subdivision of section by Arthur R. Rambo, Cadastral Surveyor under Group No. 2757, surveyed June/July 2014 - (DCSO records Vol. 58 Page(s) 23294)

The ¼ sec. cor. of secs. 26 & 35, perpetuated by the Douglas Co. Surveyor's Office in 1969, and further perpetuated by the Jackson County Surveyor's Office, in 1988; monumented with an iron post, 1" dia., firmly set, projecting 15" above the ground, with brass cap (properly) mkd.

from which the remains of original bearing trees

A sawed fir stump, 32" dia., bears N.70°E., 10.6 ft., with a healed blaze.

A sawed fir stump, 34" dia., bears S.18°W., 4.0 ft., with a healed blaze.

and new bearing trees

A cedar, 5" dia., bears N.22½°E., 4.8 ft., mkd. X at breast height and BT at base.

A fir, 5" dia., bears S.10°E., 11.1 ft., mkd. X at breast height and BT at base.