

PRIMARY CORNER DESCRIPTION Corner No. 9 HES 186, Tract A

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

HES No. 186 by Frederick W. Rase, surveyor, under special instructions dated Feb. 3, 1916 - Surveyed Sept. 1916 - DCSO records Vol. 34 Page(s) 14068)

Intersect line bet. secs. 21 & 28, east 29.05 chs from the ¼ sec. cor. bet. secs. 21 & 28 and west 10.78 chs from cor. of secs. 21, 22, 27, & 28, identical with cor. No. 1 of this survey.

At point of intersection:
Set a granite stone 25x8x8", 15" in the ground, over a stone mkd. with a cross for cor. No. 9 of this survey, mkd. CC on SW face and 9 HES 186 on side facing the claim, from which
A fir 18" dia., bears S.1°45'E., 144 lks. mkd: X 9 HES 186
BT.

No other Bearings available; pits impracticable.
Raise a mound of earth 4 ft. base, 2 ft. high 3½ ft. dist. within the claim.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & V. Perron - Dec. 31, 1969 - C.S. File 54/91-97

Found - OBT as follows
Orig. 18, now 28" Fir S.1¾°E., 95.0 ft. now stump, we open & find "86 B" scribe & reverse, no trace of old corner stone.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T32S R2W
OFFICE 1969 COR.#9 |HES 186
New BTs- 8" D.Fir N.15°W., 35.6 ft mkd: "9 HES 186 CS BT"
10" D.Fir S.50°W., 41.5 ft. mkd: "9 HES 186 CS BT"
This corner lies on flat on Eastside of old roadway.

Leonard Herzstein, USFS - Jim Landrum and Jim Hamilton - 4/22/1982 - C.S. File 61/32-25

CONDITION REPORT
Found - 1" IP with 1969 County brass cap properly mkd. projecting 14" firmly set. 1969
10" D.Fir, S.50°W., 41.5 ft. with healed blaze. 1969
9" D.Fir, N.15°W., 35.6 ft. with healed blaze. 1969
Orig BT a 28" D. fir stump, S.1¾°E., 95.0 ft. with scribe marks "86 B" visible on previously opened blaze.
Add 3 ft dia. mound of stone. IP and brass cap now project 6"
Set 6 ft. steel fence post S.35°W., 2 ft with USFS sign #54-4