

PRIMARY CORNER DESCRIPTION Angle Point, W. Bdy, Sec. 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8454)

Set post corner of secs. 30, 31, 25 and 36, from which
A Fir 8" dia., bears S.25°W., 18 lks.
A Fir 12" dia., bears S.50°E., 73 lks.
A Fir 6" dia., bears N.66°E., 43 lks.
A Hemlock 12' dia., bears N.40°W., 20 lks.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8474)

At corner of secs. 30, 31, 25 and 36, which is a post 4" sq., 24" above ground, marked and witnessed as described by the surveyor general. I reestablish this corner as follows, at same point
Set a Fir post 3 ft. long, 4" sq., 24" in the ground, for corner of secs. 25 and 36, T32S R5W., marked: T32S S36 on SW.; and R5W S25 on NW. faces; with 1 notch on S. and 5 notches on N. edges; from which
A Fir 10" dia., bears S.25°W., 18 lks. dist., marked T32S R5W S36 BT.
A Hemlock 16" dia., bears N.40°W., 20 lks. dist., marked T32S R5W S25 BT.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8590-91)

Intersect E. bdy. of Tp. 159 lks. N. of cor. of secs. 25, 30, 31 and 36, which is gone; I reestablish the cor. by setting a Hemlock post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 25, 30, 31 and 36, marked T32S S30 on NE.; R4W S31 on SE.; S36 on SW.; and R5W S25 on NW. faces, with 5 notches on N. and 1 notch on S. edges, from which
A Fir 24" dia., bears N.22°E., 86 lks. mkd. T32S R4W S30 BT. (New BT.)
A Fir 40" dia., bears S.83°E., 12 lks. mkd. T32S R4W S31 BT. (New BT)
A Fir 8" dia., bears S.25°W., 18 lks. mkd. T32S R5W S36 BT. (Old BT)
A Hemlock 12" dia., bears N.40°W., 20 lks. mkd. T32S R5W S25 BT. (Old BT)
I destroyed all marks referring to secs. 25 and 36.

(Cont. Next Page)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by Arnold Gibson, Oregon State Board of Forestry -
Wit: Lloyd D. Smith - May 30, 1972 - C.S. File 55/233-16

(Original corner 30, 31, 25 and 36)
Original post missing, from which
8" Fir bears S.25°W., 18 lks., missing
12" Fir bears S.50°E., 73 lks. missing (destroyed by
Nicklin, 1896), root holes in place.
6" Fir bears N.66°E., 43 lks.; missing (destroyed by
Nicklin, 1896), covered by fresh logging slash.
12" Hemlock bears N.40°W., 20 lks., missing.
1896 post, missing, by Nicklin.
1900 Hemlock post, missing, by Thiel, from which a
24" Fir bears N.22°E., 86 lks.; now 16" x 10 ft. rotten
stub, in place, no face.
40" Fir bears S.83°E., 12 lks.; now 46" windfall snag,
found back cast B and scribes SW.
17" W.Fir (not recorded) bears N.56°W., 54.0 ft.; face
opened, scribes T32S R5W S visible at 50 years.
Set 1½" x 36" galv. iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY AP T32S S36 T32S S31 R4W 1972
RS 359" in ground, and from which
11" Fir bears N.44°E., 15.2 ft. to face, scribed T32S R4W
S31 AP BT.
10" Fir bears N.80°W., 20.1 ft. to face, scribed T32S R5W
S36 AP BT.
Set 4" x 4" x 72" white painted Cedar post, 2.5 ft. S.44°E.,
of corner pipe. Oregon State Forestry Dept. metal location
post on 11" Fir N.44°E., 15.2 ft. Also poster on 10" Fir
N.80°W., 20.1 ft.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under
Group #977 Surveyed, May/June 1979 - (DCSO records Vol. 43
Page(s) 16762)

CORNER REPORT ONLY

Beginning at the cor. of secs. 25, 30, 31 and 36, on the E.
bdy. of Tp., established by Ives and Hyde in 1854, changed to
a cor. of minimum control by Chapman and Nicklin, in 1897,
and subsequently changed to an angle point by Thiel, in 1901,
perpetuated and recorded by Arnold Gibson, #359, in 1972,
monumented with a galv. iron pipe, 1½" dia., firmly set,
projecting 3" above ground, with bronze cap mkd.

(Cont. Next Page)

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 100167

PRIMARY CORNER DESCRIPTION AP, W. bdy. Sec. 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

OREGON STATE BOARD OF FORESTRY

T32S AP T32S

S36 | S31

R5W | R4W

1972

RS 359

from which the remains of bearing trees mkd. by Thiel

A decayed Fir stump 24" dia., bears N.18°E., 88 lks. dist.,
no marks remaining. (Rec. N.22°E., 86 lks.)

A roothole bears S.83°E., 15 lks. dist., alongside of
which is lying a decayed Fir, 40" dia., no marks
remaining. (Rec. 12 lks.)

and the remains of a bearing tree recorded by Gibson

A rotted White Fir stump 17" dia., bears N.56°W., 82 lks.
dist., with scribe marks S5S visible on decayed portion
of blaze.

and bearing trees mkd. by Gibson

A Fir 12" dia., bears N.37½°E., 23½ lks. dist., with
scribe marks T32S R4W visible on partially healed
blaze.

A Fir 12" dia., bears N.81¼°W., 30½ lks. dist., with
healed blaze.