

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 100268

PRIMARY CORNER DESCRIPTION Sec. Cor. for 24 and 25 only, T32-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8454)

Set post corner of secs. 19, 30, 24 and 25, from which
A Laurel 5" dia., bears N.53°E., 85 lks.
A Laurel 10" dia., bears S.41°E., 130 lks.
A Laurel 3" dia., bears S.11°W., 98 lks.
A Laurel 3" dia., bears N.7°W., 58 lks.

GLO survey by W.H. Byars, under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8581-82)

Intersect township line. Timber witness trees and post burned. Set post and threw up stone mound.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896. (DCSO records Vol. 20 Page(s) 8538-39)

Found a post, 24" above ground, marked and witnessed as described by the surveyor general. I reestablish this corner as follows:

Set a Fir post, 3 ft. long, 4" sq., 24" in the ground for corner of secs. 24 and 25, T32S R5W marked: T32S S25 on SW.; and R5W S24 on NW. faces, with 2 notches on S. and 4 notches on N. edges; from which

A Madrona 5" dia., bears S.11°W., 98 lks. dist., marked T32S R5W S25 BT.

A Madrona 5" dia., bears N.7°W., 58 lks. dist., marked T32S R5W S24 BT.

(This point 12.06 chs. S. of corner to 19 and 30, T32S R4W)

Richard L. Templin Jr. - For: Sierra Land Co. - April 30, 1956 - C.S. File 42/133 and M 2-42

Found two orig. BTs:

10" Madrone S.11°W., 98 lks., no scribing.

10" Madrone N.07°W., 58 lks., no scribing.

54" line tree with notches, South, 257 ft.

Scribed New BT:

34" Fir, South 40.1 ft. mkd. S25 RE 3024 BT.

50" orig. Fir BT on NE root collar mkd. "¼ S24 BT".

Douglas Co. Surveyors Office - John Powell and crew - June 17, 1970 - C.S. File 54/114-22

Found - 1" Iron pipe at section corner. (Cont. Next Page)

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 100268

PRIMARY CORNER DESCRIPTION Sec. cor. for 24 and 25 only, T32-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

40" D.Fir, South 40.1 ft., opened for scribe "3".
Hit 2 Laurels (Orig. BTs) for bearing and distance, rotted,
possible shoots from old trees found, no scribing.
New BT - 18" D.Fir N.11°W., 58.9 ft. mkd. T32S R4W S24 CS BT.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under
Group #977 Surveyed, May/June 1979 - (DCSO records Vol. 43
Page(s) 16765)

The sec. cor. for 24 and 25 only, perpetuated and recorded by
Templin in 1956, monumented with an iron pipe 1" dia., firmly
set, projecting 5" above ground, from which the remains of
the original bearing trees

A roothole bears N.53°E., 85 lks. dist.

A roothole bears S.41°E., 130 lks. dist., alongside of
which is lying a rotted madrone, 12" dia., with healed
double blaze.

A Madrone 12" dia., bears N.7°W., 58 lks. dist. with
healed double blaze.

A Madrone 12" dia., bears S.11°W., 98 lks. dist. with
decayed blaze.

and a bearing tree mkd. by Templin

A Fir 37" dia., bears S.0½°W., 61 lks. dist., with scribe
marks 02 visible on partially healed blaze.

and a bearing tree mkd. by Powell in 1970

A Fir 21" dia., bears N.11°W., 89½ lks. dist., with healed
double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in
the ground, directly over the iron pipe, with brass cap
marked T 32 S

R 5 W R 4 W

S 24 | S 30
S 25 |

1979

Fd USBLM BCIP & accessories per previous renewal by K.
DeGroot, 10/14/2005 - M148-56