

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION NW Tsp. cor. (NW Cor. Sec. 6)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and Geo. Hyde under Contract #39 dated Jan. 4, 1854 (DCSO records Vol. 18 Page(s) 7781)

Set post, cor. of Tps. 31 and 32 S., Rs. 4 and 5 W., from which

- A Fir 5" dia., bears N.15°W., 22 lks.
- A Fir 18" dia., bears N.62°E., 33 lks.
- A Fir 10" dia., bears S.55°E., 104 lks.
- A Fir 3" dia., bears S.75°W., 47 lks.

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 18 Page 7782)

Found all witness trees destroyed except one. Stake rotted off at the ground, stub remaining in place. Witness tree:

- A Fir 24" dia., bears N.62°E., 33 lks. dist.

GL0 survey by Wm. M. Bushey, under Contract #620 dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7853)

The post cor. to tps. 31 and 32 S., Rs., 4 and 5 W is gone. I find 1 witness tree.

At cor. point

Set a stone, 16x10x10 ins., 12" in the ground, for cor. to tps. 31 and 32 S., Rs., 4 and 5 W marked with 6 notches on each edge; from which

- A Fir 18" dia., (24" now) bears N.62°E., 33 lks. dist., marked T31S R4W S31 BT.

The other witness trees have been destroyed by fire.

I mark 3 new trees as follows:

- A Fir 36" dia. bears S.76°E., 40 lks marked T32S R4W S6 BT
- A Fir 10" dia. bears S.66°W., 57 lks marked T32S R5W S1 BT
- A Fir 10" dia bears N.13½°W. 82 lks marked T31S R5W S36 BT

Survey by John H. Markham, Jr. - Wit: Martin Perry - May 14, 1951 - C.S. File 40/312-2

Determined by O.B.T.

- A Fir 54" dia., bears S.73°E., 26.0 ft. (O.B.T.)
- A Fir stump, logged, 24" dia., bears N.67°E., 21.0 ft. (O.B.T.) I marked on top of stump, S31 BT.
- A Fir 20" dia., bears S.63°W., 38.0 ft. (O.B.T.)

At corner point, set 3/4" x 24" Iron pipe and found original stone, from which

- A Fir 7" dia., bears N.82°E., 10.0 ft. mkd. S31 BT.

continued next page

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION NW Tsp. Cor. (NW Cor. Sec. 6)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by Richard Templin Jr. - Sept. 1958 - C.S. File 42/389

Found - 3/4" iron pipe (unmarked)
24" Fir S.62 3/4°W., 39.5 ft. blaze healed.
50" Fir stump S.74½°E., 25.5 ft. scribing visible.
40" Fir stump N.65°E., 20.0 ft. blaze healed.
16" Fir stump N.16°W., 54.0 ft. blaze healed.
10" Fir N.79 3/4°E., 9.8 ft. scribing visible.
Scribed: 6" Cedar N.27°W., 16.6 ft. mkd. S36 RE 3024 BT.

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCS0 records Vol. 38 Page(s) 15641)

The Tsp. corner, perpetuated and recorded by Templin in 1958, monumented with an iron pipe 1" dia., firmly set, protruding 6" above ground, alongside of which is a basalt stone, 16 x 10 x 10 ins., loosely set, 2" in the ground, mkd. with 6 notches on each edge, from which the remains of the original bearing trees:

A Fir stump 39" dia., bears N.62°E., 33 lks. dist., no marks visible.
and the remains of bearing trees mkd. by Bushey:
A Fir stump 65" dia., bears S.76°E., 40 lks. dist., with scribe mark S visible on opened blaze.
A Fir 35" dia., bears S.62°W., 60 lks. dist., with healed blaze. (Record, S.66°W., 57 lks.)
and a bearing tree mkd. by Templin:
A Cedar 8" dia., bears N.25½°W., 25 lks. dist., with healed blaze.

At the corner point
Set an iron post 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T 31 S
R 5 W R 4 W
S 36 | S 31
S 1 | S 6
T 32 S
1973

from which new bearing trees
A Fir 14" dia., bears N.63°E., 47 lks. dist., marked T31S R4W S31 BT.
A Fir 12" dia., bears S.50°E., 53 lks. dist., marked T32S R4W S6 BT.
Deposit iron pipe and stone alongside iron post.

Fd. OK - R. Templin - July 1994 - 1995-0115 A&B

cont

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION NW Tsp. cor. (NW Cor. Sec. 6)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Arthur R. Rambo, Cadastral Surveyor under Group No. 2707, surveyed April/May 2013 - (DCSO records, Vol. 58 Page(s) 23126-7)

The cor. of Tps. 31 & 32 S., Rs. 4 & 5 W., monumented with an iron post, 2½" dia., firmly set, projecting 2" above the ground with brass cap (properly) mkd.

from which the remains of an original bearing tree
A sawed fir stump, badly decayed, 38" dia., bears N.62°E., 21.8 ft., no marks visible.

and the remains of bearing trees mkd. by Bushey in 1894
A sawed fir stump, 63" dia., bears S.74°E., 28.0 ft., with illegible scribe marks visible on open blaze. (Record, S.76°E., 26.4 ft.)

A fir, 42" dia., bears S.62°W., 38.9 ft., with a healed blaze. (Record, 39.6 ft.)

and a bearing tree mkd. by Templin Jr., RPE No. 3024, in 1958
A cedar, 16" dia., bears N.27°W., 16.5 ft., with a healed blaze. (Record, N. 25½°W.)

and the remains of BTs mkd. by Berry and Akin Jr. in 1972-73
A fir, 25" dia., bears N.63°E., 31.0 ft., with a healed blaze.

A sawed fir stump, 18" dia., bears S.50°E., 35.0 ft., with a healed blaze.

and a new bearing tree
A fir, 8" dia., bears S.56¾°E., 22.9 ft., mkd. X at breast height, and BT at base.

NAD 1983 (2011)
Latitude: 42°49'33.58" N. Longitude: 123°13'42.07"W.

Ron Quimby - Crew: N. Fromdahl & R. Olson - 9/2015 - C.S. File 65/89-41

Found - 3" BLM brass cap (properly mkd)
38" fir stump N.62°E., 21.8 ft. - badly decayed
25" fir N.63°E., 31.0 ft. - Good scar.
63" fir stump S.74°E., 28.0 ft. - Vis. scar.
18" fir stump S.50°E., 22.9 ft. - Good scar.
42" fir S.62°W., 38.9 ft. - Good scar.
17" cedar N.27°W., 16.5 ft. - Good scar.

Note - Corner is on a NE slope approx. 500' west of road.
N 42°49'33.58" W 123°13'42.07"
Compass decl. 15½°E.