

PRIMARY CORNER DESCRIPTION A.P. #2, S. bdy Sec. 31

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by McKenzie and Eckelson, Deputy Surveyors, under Contract #328, dated June 17, 1879 - (DCSO records Vol. 20 Page(s) 8466)

Set post for corner to Tp. 32 S. R. 4 and 5 W.
A Fir 12" dia., bears N.41°E., 18 lks.
A Fir 9" dia., bears N.68°W., 19 lks.
After diligent search I failed to find the corner and establish the one as described above.
Witness trees evidently destroyed by fire.

GLO survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8928)

Standard cor. to Tps. 32 S R 4 and 5 West which is a post 4½ ft. long, 4" sq., lying loose upon the ground, marked S C T32S on N.; R4W S31 on E.; R5W S36 on W.; faces with 6 notches on N. E. and W. faces, from which
A Fir 12" dia., bears N.41°E., 18 lks. dist., marks pitched over well defined blaze.
A Fir 9" dia., bears N.68°W., 19 lks. dist., marks pitched over well defined blazes.
At exact point for cor. I set a basaltic stone, 12 x 12 x 10 ins., 8" in the ground, marked with S C and 6 notches on N., E. and W. edges, and also reset post 12" in the ground by the side of stone for cor. This cor. is about 400 ft. above point for closing cor. to secs. 1 and 6.

BLM resurvey by Lynn Roseberry and Rollin Aanrud, Cadastral Surveyors, under Group #865, surveyed July/Oct. 1975 (DCSO records Vol. 42 Page(s) 16539)

Point for the former standard cor. of Tps. 32 S., Rs. 4 and 5 W., changed to an angle point by Chapman and Nicklin, determined by the method of irregular boundaries, there is no remaining evidence of the original corner.
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
AP 2
T 32 S R 4 W
S 31
1975
from which
A Fir 27" dia., bears N.49°E., 56½ lks. dist., mkd. AP 2 S31 BT.
A Fir 25" dia., bears N.25°W., 61 lks. dist., mkd. AP 2 S31 BT.