

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; and 31 of T31-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 18 Page(s) 7782)

-----  
Set ¼ sec. post, from which  
A Fir 20" dia., bears N.20°E., 40 lks. dist.  
A Fir 30" dia., bears S.45°W., 9 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7853)

-----  
Set temp. stake and make diligent search for the ¼ sec. cor. which I am unable to find. Fires have destroyed all traces of this cor. and the witness trees also.

Reported as not found 2/1966 DCSO C.S. 54/20-37A

Survey by Richard Templin, for Superior Lumber, July 1994, M120-58; C.S. 63/130.

-----  
Set At proportionate distance, 5/8" iron rod with yellow plastic cap marked "TEMPLIN LS 2359"  
BTs - D.Fir, 4" dia. bears N.50°E., 13.2 ft. scribed "¼ S31"  
"BT"  
Cedar, 12" dia. bears S.69°E., 35.2 ft. scribed "¼ S6"  
"BT"  
D.Fir, 8" dia. bears S.42°W., 17.1 ft. scribed "¼ S6"  
"BT"  
D.Fir, 10" dia bears N.61°W., 24.7 ft. scribed "¼ S31"  
"BT"

Daniel Baker - For: Weyerhaeuser - 7/2019 - M176-18A-C

-----  
Found - 5/8" iron rod with yellow plastic cap "TEMPLIN LS 2359" per M120-58  
10" Fir, N.49°E., 13.2' (REC.= N.50°E., 13.2') to nail side/center - M120-58 BT  
20" Cedar, S.69°E., 35.3' (REC.=S.69°E., 35.2') to nail side/center - M120-58 BT  
9" Fir, S.41°W., 17.3' (REC. = S.42°W., 17.1') to nail side/center - M120-58 BT  
14" Fir, N.61°W., 24.8' (N.61°W., 24.7') to nail side/center - M120-58 BT