

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 168400

PRIMARY CORNER DESCRIPTION CC Secs. 19 & 20 only (on S. bdy. Sec. 18)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8540)

Set a Fir post 3 ft. long, 4" sq., 24" in the ground for closing corner of secs. 19 and 20, marked C C T32S R4W on S.; S20 on E.; and S19 on W. faces, with 3 grooves on S. and 5 grooves on E. faces; from which

A Fir 36" dia., bears S.76°E., 41 lks. dist., mkd. T32S R4W S20 BT.

A Fir 8" dia., bears S.45°W., 51 lks. dist., mkd. T32S R4W S19 BT.

This corner is on a NE. slope, 50 ft. above creek.

George J. Wenderoth, Deputy Co. Surveyor - Wit: Frank Loso & Wenderoth - July 1948 - C.S. File 39/159

Found one BT badly rotted.

Set 1" Iron pipe for corner.

Mark - 18" Fir N.86°10'W., 76.4 ft.

8" Hemlock S.28°E., 45.0 ft.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - May 8, 1970 - C.S. File 54/114-15

Found - 1" Iron pipe at closing corner.

18" D.Fir now stump, S.86°W., (Rec. N.86°W.) 76.4 ft scribe visible "S19 CS BT".

8" now 14" Hemlock S.28°E., 45.0 ft. shows good scar

New BT - 8" D.Fir S.86°W., 48.6 ft. mkd. T32S R4W S19 CC CS BT.

This corner lies in logged area in bottom of ravine, running North.

Fd 1" IP, with 90° elbow attached, as per record - 2/2020 by R Brown - M176-60