

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Section 17 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8543)

Set a Fir post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. corner, marked ¼ S on N. face; from which
A Madrona 12" dia., bears N.15°W., 11 lks. mkd. ¼ S BT.
A Madrona 10" dia., bears S.8°E., 7 lks. mkd. ¼ S BT.
This corner is on the SW. slope of spur, 50 ft. below top.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - May 12, 1970 - C.S. File 54/114-20

Found - 10" Laurel, now down, S.8°E., 4.6 ft., faint rotten scribe visible.
12" Laurel, now down, N.15°W., 7.3 ft. rotten scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R 4 W
¼ S 8
S 17
1970

New BTs -38" D.Fir N.40°E., 26.3 ft. mkd. ¼ S8 CS BT.
38" D.Fir S.59°E., 31.3 ft. mkd. ¼ S17 CS BT.

BLM resurvey by Larry Evans, Cadastral Surveyor under Group #736, surveyed May/June 1971 (DCSO records Vol. 37 Page(s) 15349)

The ¼ sec. cor. of sec. 17 only, perpetuated and recorded by the County in 1970, monumented with an iron pipe, 1" dia., protruding 14" above the ground, firmly set, with brass cap mkd. COUNTY SURVEYORS OFFICE T32S R4W 1/4 S8|S17 1970, from which the remains of the original 1897 bearing trees:

A root hole bears N.15°W., 11 lks. dist., alongside of which is lying the remains of a decayed Madrone 12" dia., no marks visible on opened and decayed blaze.

A root hole bears S.8°E., 7 lks. dist., alongside of which is lying the remains of a decayed Madrone 11" dia., no marks visible on opened and decayed blaze.

and bearing trees mkd. by the County

A Fir 39" dia., bears N.40°E., 40 lks. dist., with scribe marks ¼ S8 CS BT visible on partially healed blaze. I destroy the scribe marks on this tree.

A Fir 39" dia., bears S.59 3/4°E., 47½ lks. dist., with scribe marks ¼ S17 CS BT visible on partially healed blaze.

(Cont. Next Page)

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Section 17 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
with brass cap mkd: T 32 S R 4 W

1/4 S 17
1971

from which a new bearing tree

A Fir 35" dia., bears S.18p°W., 68½ lks. dist., mkd. ¼ S17
BT.

Invert and deposit county pipe alongside iron post.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause,
crew - Oct. 30, 1990 - C.S. File 64/11-1

Found - 3½" dia. 1971 BLM brass cap on an iron pipe found
flush with ground.

A DCSO 1½" O.D. flanged iron pipe is found inverted,
protruding 15" above ground. Inverted in 1971
BLM resurvey. DCSO I.P. bears North, 0.5 ft.
from BLM BC/IP.

12" Madrone now root hole with remains of decayed
Madrone alongside, no blazes or scribing visible,
root hole bears N.15°W., 7.3 ft. (agrees w/rec)
Orig. BT.

Orig. SE BT is gone.

38" now 42" dia. D.Fir with a fully healed single
blaze bears S.59°E., 31.3 ft. (agrees w/rec)

35" now 35" dia., 2½" high D.Fir stump, no blazes or
scribing visible bears S.18½°W., 45.2 ft. (agrees
w/rec)

New BTs - 28" dia. 1½ ft. high D.Fir stump, set 8" boat spike
through BT tag near top center of stump, stamped
"BO1", boat spike bears S.73°E., 68.4 ft.

36" dia. 4 ft. high D.Fir stump, set 8" boat spike
through BT tag near top center of stump, stamped
"BO2", boat spike bears S.20°E., 49.0 ft.

Corner lies on a southerly slope in a new clear cut. Approx.
700 ft. north of gravel road.