

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8460)

Set ¼ sec. post, from which
A Fir 16" dia., bears N.52°W., 25 lks. dist.
A Fir 36" dia., bears S.80°E., 27 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8532)

The ¼ sec. corner, which is a post badly decayed; and which I reestablish at same point as follows:
Set a basalt stone 12x10x8 ins., 8" in the ground for ¼ sec. cor., mkd. ¼ on N. face; from which
A Fir 16" dia., bears N.52°W., 25 lks. mkd. ¼ S BT.
A Fir 36" dia., bears S.80°E., 27 lks. mkd. ¼ S BT.

Survey by Bruce A. Shaner - For: Aggson & Harrison - June 1963 - RM 1-37

Set 5/8" x 36" rod by proportionate measurement, from which,
40" D.Fir bears S.69°W., 50.4 ft. scribed ¼ S S8 T32S R4W.
38" D.Fir bears N.8°W., 59.0 ft. scribed ¼S S5 T32S R4W BT

Survey by Kristian DeGroot L.S. #1941 - For: Roseburg Resources and S. Jantzer - Nov. 1990 - C.S. File 63/52 and M 111-12

Found - 5/8" Iron rod firmly set, projecting 10" above ground as set by Shaner in 1963.
36" D.Fir bears S.70°W., 51.4 ft. with a healed blaze. (Rec. S.69°W.)
36" D.Fir bears N.08°W., 60.8 ft. with a partially healed blaze.
Removed 5/8" Iron rod and in its exact position:
Set a 1" x 30" Iron pipe 18" in the ground in a 2 ft. dia. mound of stone with a 2½" brass cap. Reset the 5/8" Iron rod on the N. edge of the brass cap w/iron pipe.

B.C. Fd. OK, by Bruce Rogers, October 1993, Land partition, 1993-0082

continued next page

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 5 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Mark Smalley - For: Roseburg Resources - 11/ 2005 thru 1/2006
- M150-7

Found - 1990 IP.BC marked PLS 1941
48" D.Fir S.70°W., 51.4' record S.69°W., 50.4', snag
healed face.
39" D.Fir N.8°W., 60.8' record N.8°W., 59.0', good
cond. Healed face.
6" D.Fir S.89°E., No record, good cond. Healed face
Scribed "¼ BT"
9" D.Fir N.71°W., 14.6'
15" D.Fir N.51°E., 11.3'

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor,
under Group No. 2627; Surveyed April/May 2013 - (DCSO records
Vol. 58 Page(s) 23063-4)

the 1/4 sec. cor. of secs. 5 and 8, reestablished by
proportionate measurement by Shaner, in 1963, perpetuated by
DeGroot, in 1990, and further perpetuated by Smalley, in
2005-06. There is no remaining evidence of the original cor.
and this position is accepted as a careful and faithful
reestablishment of the cor.; monumented with an iron post, 1"
dia., firmly set, projecting 4" above a mound of stone, 3 ft.
base, 1 ft. high, with brass cap (properly) mkd.
from which bearing trees mkd. by Shaner
A fir, 41" dia., bears S.70°W., 51.5 ft., with a healed
blaze.
A fir, 41" dia., bears N.8¼°W., 60.9 ft., with a healed
blaze.
and bearing trees mkd. by Smalley
A fir, 17" dia., bears N.53¼°E., 11.7 ft., with illegible
scribe marks visible on partially healed blaze.
A fir, 10" dia., bears N.67°W., 13.9 ft., with a healed
blaze.
An iron rod, 5/8 in. diam., is alongside the iron post.

NAD 1983 (2011)
Latitude: 42°49'35.83" N. Longitude: 123°11'21.93" W.