

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 3 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8505)

Set a Madrona post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. corner, marked 1/4 S on N. face, from which
A Fir 14" dia., bears N.53°W., 140 lks. dist., mkd. 1/4 S BT
A Fir 10" dia., bears S.14°E., 113 lks. mkd. 1/4 S BT.
This corner is on the S. slope of mountain, 150 ft. above spur.

GLO resurvey by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 20 Page(s) 12782-83)

Point for the 1/4 sec. cor. of sec. 3 at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd: 1/4 S 3
T32S R4W
1959
from which
A Madrona 7" dia., bears N.11°E., 12 lks. mkd. 1/4 S3 BT.
A Madrona 6" dia., bears N.12 1/2°W., 9 lks. mkd. 1/4 S3 BT.

Tony Hostetter - For: Seneca Jones Timber Co. Co. - April 2006 - M150-60

Found - 1959 BLM brass cap & both BTs as described by Thielsen Vol. 30 Pg 12782-83) from which:
New BTs- 16" Fir scribed "S3 1/4 BT", bears S.45°W., 23.5 ft. to spike.
10" Fir scribed "3 1/4 BT", bears N.50°W., 9.1 ft. to spike.