

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8494)

Set a Pine post, 3 ft. long, 4" sq., 24" in the ground, for 1/4 sec. corner, marked 1/4 S on W. face, from which
A Madrona 6" dia., bears N.73°E., 10 lks. mkd. 1/4 S BT.
A Fir 48" dia., bears N.15°W., 23 lks. mkd. 1/4 S BT.
This 1/4 cor. is on the SW. slope of spur, 125 ft. above creek.

Survey by H.L. Eppstein, Co. Surveyor, made by Bert Lane - For: Clare Lumber Co. - July 1937 - C.S. File 15/25 and M 6-6 (and "old" corner book, page 170)

Set a post from old BTs. Laurel rotted & Fir down, marks visible
Marked new BT:
A 16" Fir N.71 1/2°E., 33.0 ft. mkd. 1/4 S CS BT.
A 30" Fir S.18 1/2°W., 27.0 ft. mkd. 1/4 S CS BT.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12795-96)

The 1/4 sec. cor., determined at record bearing and distance from the remaining original bearing tree:
A Fir 50" dia., bears N.15°W., 23 lks. marked with an opened blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd: 1/4
S 22 | S 23
T32S R4W
1959
from which new bearing trees
A Fir 20" dia., bears N.69°E., 47 lks. mkd. 1/4 S23 BT.
A Fir 48" dia., bears S.19°W., 44 lks. mkd. 1/4 S22 BT.

Greg Lang, July 1995 - M122-46

Found - Brass Cap
21 1/2" Stump, Bears N.69°E. 47 lks.
48" Stump, bears S.19°W. 44 lks.
(no rec.) 27" Chinq N.50°W. 2.5', has a Longview Fibre tag.

Fd. cor. as per M122-46 by D. Edwards 11/2010 - M161-51