

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; and 34 & 35, T31-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 18 Page(s) 7784)

-
- Set post, cor. to secs. 2, 3, 34 and 35, from which
- A Fir 6" dia., bears N.40°E., 130 lks. dist.
 - A Fir 10" dia., bears S.25°E., 15 lks. dist.
 - A Fir 5" dia., bears S.62°W., 14 lks. dist.
 - A Fir 5" dia., bears N.22°W., 23 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7814)

-
- The Sec. cor., which is a post, 3½" sq., firmly set, marked T31S S35 on NE.; R4W S2 on SE.; T32S S3 on SW.; and S34 on NW. faces; with 2 notches on E. and 4 notches on W. edges, from which
- A Fir (hemlock) 6" dia., (10" now) bears N.40°E., 13 lks. (not 130 lks. as stated in notes) dist., marked T31S R4W S35 BT.
- The witness trees in secs. 2, 3 and 34 are down.
I mark 3 new trees as follows:
- A W.Fir 14" dia., bears S.50°E., 61 lks. dist., mkd. T32S R4W S2 BT.
 - A Fir 8" dia., bears S.51½°W., 40 lks. dist., mkd. T32S R4W S3 BT.
 - A Fir 7" dia., bears N.16°W., 61½ lks. dist., mkd. T31S R4W S34 BT.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12788)

The Sec. cor., perpetuated with an axle shaft, 1" dia., set by the County Surveyor in 1950, from which a bearing tree mkd. in 1950:

- A Fir 12" dia., bears S.62°E., 91 lks. dist., mkd. with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked

T31S R4W
<u>S 34 S 35</u>
S 3 S 2
T32S
1959

from which new bearing trees

- A Cedar 14" dia., bears N.30°E., 134 lks. dist., mkd. T31S R4W S35 BT. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; and 34 & 35, T31-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

An Alder 10" dia., bears S.40½°W., 74 lks. dist., mkd. T32S R4W S3 BT.
A Fir 5" dia., bears N.70½°W., 147 lks. dist., mkd. T31S R4W S34 BT.
Reset axle shaft alongside iron post.

BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15465)

The Sec. cor., monumented with an iron post 2½" dia., firmly set, protruding 8" above ground, with 1959 brass cap. from which the remains of a bearing tree mkd. by the County in 1950:
A sawed Fir stump 14" dia., bears S.62°E., 91 lks. dist., with healed double blaze.
and bearing trees mkd. by Thielsen:
A Cedar 22" dia., bears N.30°E., 105 lks. dist., with healed blaze. (Rec. 134 lks.)
An Alder 14" dia., bears S.40½°W., 74 lks. dist., with scribe marks T32S R4W S3 BT visible on partially healed blaze.
A Fir 15" dia., bears N.70½°W., 137 lks. dist., with healed blaze. (Rec. 147 lks.)
and new bearing trees:
A Fir 16" dia., bears S.83¼°E., 259 lks. dist., mkd. T32S R4W S2 BT.
A Fir 11" dia., bears S.57½°W., 41 lks. dist., mkd. T32S R4W S3 BT.
(No recorded information could be found regarding "1950" county visit to this corner. Corner now under Galesville Dam.)

Kris DeGroot - For: Silver Butte Timber - 3/2008 - M146-71

The USBLM brass capped iron post monument by Thielsen in 1959 is now missing having been destroyed by the construction of Galesville Reservoir the corner position is computed from existing bearing trees per the Roseberry & Evans record of 1972 but was not monumented. The corner position is under water during normal reservoir levels but is accessible at low pool levels during winter months.
From which a bearing tree by DCSO in 1950:
A 14" fir stump bears S.62°30'E., 63.6 ft (record S.62°E., 91 lks.)
And bearing trees by thielsen in 1959:
A 29" cedar snag bears N.30°15'E., 89.0 feet (record N.30°E., 134 lks.) continued next page

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; and 34 & 35, T31-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 23" fir snag bears N.69°15'W., 90.4 ft (record N.70°30'W. 137 lks.)
And bearing trees by Roseberry & Evans in 1972:
A 20" fir snag bears S.83°15'E., 170.9 ft (record S.83°15'E., 259 lks.)
A 18" fir snag bears S.57°15'W. 27.1 ft (record S.57°30'W. 41 lks.)

Witness Corner

At a point which bears S.89°55'34"E., 230.00 ft from the section corner common to sections 2, 3, 34 and 35 I established a witness corner as follows:

Set - A 1½"x36" iron post, 36" in the ground with 2½" brass cap stamped:

	230.00 ft
←	T31S R4W WC
	S 34 S 35
	S 31 S 2
	T32S
	2008
	PLS 1941

from which new bearing trees:

- A 7" W.Fir bears N.0°15'W., 14.3' ft scribed "T31S R4W S35 WC BT".
- A 11" D.Fir bears S.63°E., 41.2' ft. Scribed "T32S R4W S2 WC BT".

And new reference monuments:

- A 5/8"x30" iron rod on the northerly right of way line of Cow Creek County Road No. 36 bears S.89°55'34"E., 283.88 feet.
- A ¾" iron rod on the northerly right of way line of Cow Creek Co. Road No. 36 bears N.11°58'30"E., 413.45 ft