

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8495)

Set a Fir post, 3 ft. long, 4' sq., 24" in the ground for ¼ sec. corner, marked ¼ S on N. face; from which
A Fir 24" dia., bears N.4°E., 22 lks. mkd. ¼ S BT.
A Fir 10" dia., bears S.65°W., 34 lks. mkd. ¼ S BT.
This corner is on the NE. slope of spur, 25 ft. above creek.

Survey by Richard Templin, Jr. - For: So. Oregon Plywood Corp. April/May 1956 - C.S. File 42/159

Monument with a slate stone 12x10x5 inches marked ¼ on the North face, from which
40" D.Fir bears N.16°W., 14.5 ft. blaze healed.
16" D.Fir bears S.52°W., 22.4 ft. blaze healed.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12796-97)

The ¼ sec. cor., determined at record bearing and distance from each of the original bearing trees:
A sawed Fir stump 34" dia., bears N.4°E., 22 lks. marked with a healed blaze.
A Fir 15" dia., bears S.65°W., 34 lks. marked with a healed blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd:
¼ $\frac{S\ 14}{S\ 23}$
T32S R4W
1959
from which a new bearing tree
A Hemlock 14" dia., bears N.31°E., 74 lks. mkd. ¼ S14 BT.

David Edwards - For: Seneca Jones Timber Co. & Silver Butte Timber Co. - 3/2009 - M 159-4

Found - Brass cap
40" Fir S.65°W., 22.4' with healed blaze.
New BT - 16" dia., yew bears S.27°E., 21.2 ft., measured to center of tree at root crown.
No trees available in Sec. 14.
6 ft. steel post set 2' north.