

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8467)

Set a basalt stone 12 x 8 x 7 ins., 8" in the ground for 1/4 sec. corner, marked 1/4 on N. face, from which
 A Fir 42" dia., bears N.9°W., 53 lks. dist., mkd. 1/4 S BT
 A Fir 12" dia., bears S.30°E., 50 lks. dist., mkd. 1/4 S BT
This 1/4 sec. corner is on a hillside, sloping SE., about 600 ft. above creek.

Douglas Co. Surveyors Office - John M. Powell, J Heritage, W. Penley, crew - May 28, 1970 - C.S. File 54/114-40

Found - 12x8x7 stone, firmly in place, mkd. 1/4 on N. face.
 42" D.Fir now snag N.9°W., 35.0 ft. burnt face, faint scribe marks visible.
 No trace of SE BT due to old logging.
Set Brass cap at cor. mkd: County Surveyors Office
 T 32 S R 4 W
 1/4 $\frac{S \ 25}{S \ 36}$ Doug Co
 Jack Co
 1970
New BTs -12" W.Fir N.75°W., 6.3 ft. mkd. 1/4 S25 CS BT.
 6" D.Fir S.56°E., 19.8 ft. mkd. 1/4 S36 CS BT.

BLM Dependent resurvey by Ernest Q. Lundeen, Cadastral Surveyor, under Group No. 2916, surveyed June/Nov. 2018 - (DCSO records Vol. 59 Pages 23931-23932 & T32-4 Plat 2021-1)

The 1/4 sec. cor. of secs. 25 and 36, perpetuated by the Douglas County Surveyor's Office in 1970; monumented with an iron post, 1 1/2" dia., firmly set, projecting 18" above ground in a collar stone with brass cap (properly) mkd. from which the remains of an original bearing tree
 A fir snag, 32" dia., bears N.9°W., 35.0 ft., with illegible scribe marks visible on rotted blaze.
and BTs mkd. by the Douglas County Surveyor's Office
 A fir, 24" dia., bears S.56 1/4°E., 20.4 ft., with a healed blaze.
 A fir, 19" dia., bears N.75 1/2°W., 5.4 ft., with a partially healed upper blaze marked for line and lower healed double blaze.