

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; and Sec. 36, T31-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 18 Page(s) 7785)

-----  
Set ¼ sec. post, from which  
A Fir 8" dia., bears North, 43 lks. dist.  
A Fir 12" dia., bears S.40°E., 12 lks. dist.

George J. Wenderoth, Deputy Co. Surveyor - For: H.D. Hauck - May 1955 - C.S. File 46/134

-----  
Iron bar.  
48" Cedar S.57°09'W., 170.0 ft.  
18" Fir N.48°E., 130.4 ft.

Douglas Co. Surveyors Office - John M. Powell and crew - Jan. 17, 1966 - C.S. File 54/20-30

-----  
Found - No trace of Iron rod set by Wenderoth. This corner was in horse lot, owners wanted it reset outside lot.  
48" Cedar now 50", S.57°W., 170.0 ft. "BT" scribe visible.  
18" Fir N.48°E., 130.4 ft. This tree is dead, shows good pitched over scars.

Set Brass cap for WIT. COR., mkd: County Surveyors Office  
T 31 S  
W.C. 8' S. to ¼  $\frac{S \ 36}{S \ 1}$  R4W  
T 32 S  
1966

New BT - 7" Cedar N.79½°E., 37.0 ft. mkd. ¼ S36 CS BT.  
Brass cap in E-W wood fence.

Fd. OK, by R. Brown, April 1993, M 112-72

Fd. OK, by G. Nygren, Nov. 2996, M 124-34