

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 12; and S. 7, T32-3

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8359)

Set 1/4 sec. post, from which
A Fir 30" dia., bears N.60°E., 31 lks. dist.
A Fir 24" dia., bears S.85°W., 31 lks. dist.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12787)

The 1/4 sec. cor., determined at record bearing and distance from the remaining original bearing tree mkd. by Byars in 1871:

A Fir 24" dia., bears S.85°W., 31 lks. dist., mkd. 1/4 S3 on bark.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked

1/4
S 12 | S 7
R4W | R3W
T32S
1959

from which a new bearing tree

A Fir 18" dia., bears N.56 1/4°E., 66 lks., mkd. 1/4 S7 BT.

Kris DeGroot - For Silver Butte Timber Co. - 8/2010 - M161-16

Lat: 42°48'21.87468"N. Long: 123°06'41.75427"W.

Found - USBLM BCIP by Hans W. Thielsen, Cadastral Surveyor, in 1959 per USBLM Field note Volume OR-R0571, pages 75 & 76, firmly set, projecting 10" above the ground, properly marked:

from which the orig. BT by Byars IN 1871:

A 36" Fir high-stump bears S.85°W., 21.3 ft (rec. 31 lks. - 20.5 ft)

and a BT by Thielsen in 1959:

A 18" rotted fir stump bears N.56°15'E., 42.7 ft. (rec. 66 lks. - 43.6 ft)

New BTs- A 10" D.Fir bears N.52°E., 22.6 ft scribed "1/4 S7 BT"

A 10" D.Fir bears S.55°45'W., 12.6 ft scribed "1/4 S12 BT"

New RMs- A 5/8"x30" iron rod bears S.80°18'00"E., 17.75 ft.

A 5/8"x30" iron rod bears S.2°59'06"W., 23.95 ft.