

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; and Sec. 6, T32-3

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol 20 Pg 8359)

-----  
Set ¼ sec. post, from which  
A Fir 10" dia., bears N.68°E., 8 lks. dist.  
A Chinquapin 8" dia., bears S.65°W., 4 lks. dist.

Arthur Boyer, Douglas Co. Surveyor - Wit: Ted Shellabarger & Dick Dehrig - Sept. 23, 1940 - C.S. File 34/22 & Vol. 4 Pg 69

-----  
Set this corner from orig Fir BT, 10", which is N.68°E. 8 lks  
The orig 8" Chinquapin S.65°W., 4 lks. is entirely destroyed.  
Set a 4 x 4 Chinquapin post. Marked a new BT:  
24" Fir, N.48°W., 12 ft. mkd. ¼ S 1 T32S R4W CS BT.

George J. Wenderoth, Deputy Co. Surveyor - For: H.D. Hauck - May 1955 - C.S. File 46/134

-----  
1" Iron pipe.  
20" Fir N.68°E., 5.3 ft.  
20" Fir N.48°W., 12.0 ft.

Survey by Terrence O. Nickerson, L.S. #1649 - For: Bureau of Land Management - Oct. 1979 - M 80-71

-----  
Found - 2" dia., Iron pipe firmly set, and protruding 6" above ground.  
Remains of the remaining original bearing tree, a sawed Fir stump 21" dia., bears N.68°E., 5.3 ft. with no marks visible on rotted opened blaze.  
Bearing tree mkd. by Wenderoth, a Fir snag, 24" dia., bears N.48°W., 12.0 ft. with bark scribe marks ¼S T32S R4W visible. (Measured to face.)  
New BT - 8" Fir bears S.61 3/4°W., 14.5 ft. mkd. ¼ S1 BT.

Fd. OK - Gerald Nygren - Nov. 1996 - M 124-34  
FD. Ok by R. Brown, 2/2009 - M157-10

Ronald L. Rice, Ward NW - For: Seneca Jones Co. - Sept 2011 - C.S. File 65/74-17

-----  
Found - 1/12" O.D. Iron Pipe (record 2") with the following accessories  
21" Fir stump bears N.68°E 5.3' - rotted face  
24" Fir rotted staub bears N.48°W 12.0' - no marks  
16" Fir bears S.61¾°W 14.5' - healed face  
New BT - 18" D.Fir bears S.18°E., 16.5' - scribed "¼ S6 BT"