

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30; 24 & 25, T32-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - George W. Hyde and Wells Lake, under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8553)

Set post, cor. to secs.19, 24, 25 and 30 on S. slope, from which

- A B.Oak 12" dia., bears N.42°E., 67 lks.
- A Pine 36" dia., bears N.48°W., 28 lks.
- A W.Oak 9" dia., bears S.43°E., 57 lks.
- A B.Oak 9" dia., bears S.13°W., 82 lks.

G.J. Wenderoth, Surveyor - Wit: F. Loso and C. Smith - April 6, 1949 - C.S. File 40/268; M 32-2 and C.S. File 45/45, M 27-12

Found 2 old BTs badly rotted.
Drove 1¼" I.P. for corner.
Marked - 16" W.Oak S.43°E., 37.6 ft. (O.B.T.)
16" Pine N.78°25'E., 29.2 ft.
22" Pine N.75°15'W., 39.5 ft.
15" Fir S.25°42'W., 44.9 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Joe Brady, crew - Aug. 1967 - C.S. File 53/52-7

Found - 1½" Iron pipe at section corner.
16" W.Oak S.43°E., 37.6 ft., good scar.
16" Pine N.78°E., 29.2 ft., pitched over face.
22" Pine stump N.75°W., 39.5 ft. scribe visible "BT"
No trace of SW BT, skid road.
New BTs -14" Laurel S.87°W., 49.5 ft. mkd. T32S R6W S25 CSBT.
18" Laurel N.82°W., 71.8 ft. mkd. T32S R6W S24 CSBT.

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - Clell Goodwin; A. Vic Cangie; M. Lenora Ladig, crew - Nov. 10, 1975 - C.S. File 57/39-5

Found - 1½" I.Pipe, firmly set at fence corner, fences running N., E., and S.
An Orig. BT, a 9" now 16" W.Oak bears S.43°E., 37.6 ft. with faint scribe marks visible on previously opened blaze.
All other original evidence has been destroyed.
16" now 21" Pine, now a stump, bears N.78°E., 29.2 ft. scribe marks visible.
14" now 16" Madrone bears S.87°W., 49.5 ft. all scribes visible.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. cor. for 19 & 30; 24, 25 of T32-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>18" now 19" Madrone bears N.82°W., 71.8 ft. (dist. taken to East fork of twin-forked Madrone). All scribes visible. New BT - 10" Madrone bears N.42°E., 13.2 ft. scribed "T32S R5W S19 CS BT" on a double blaze.</p>
<p>Fd. OK, by Donald Bentz, Sept. 1986, M 102-39</p>
<p>Ray Wytcherley - For: Superior Lumber Co. - 3/2002 - M139-65 ----- Condition report Found - 1½" I. pipe firmly set & projecting 8" above the ground An OBT, a dead W.Oak 16" diam. bears S.40°E, 38.11 ft. To nail (rec. S.43°E, 57 lks) rotted face. A Pine stump mostly rotted bears N.81°E., 29.8 ft. A Madrone 20" diam. bears S.89°W., 49.24 ft. to nail (rec. S.87°W., 49.5 ft.) Some scribes visible East fork of twin forked Madrone 14 in. diam. bears N.79°W., 72.47 ft. to nail (rec, N.82°W., 71.8 ft.) Some scribes visible A Madrone 12 in. diam. bears N.38°E., 12.78 ft. to a nail (rec. N.42°E., 13.2 ft.) some scribes visible.</p>
<p>Fd. Ok by Ray Wytcherley, July 2005 - M148-25 FD. OK by Ray Wytcherley June 2018 - M174-47 A&B Fd. 1½" IP by Bart Heichel, 12/2022 - M181-68</p>
<p> </p>