

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8611)

Set a cedar post, 3 ft. long, 3" sq., 24" in ground for 1/4 sec. cor., marked 1/4 S6 on W. face and 5 on E. face, from which
A Cedar 24" dia., bears S.42°E., 37 lks. mkd. 1/4 S5 BT.
A Cedar 20" dia., bears N.18°W., 51 lks. mkd. 1/4 S6 BT.

BLM dependent resurvey by Joseph S. Gawron and Norman J. McDonald, under Group #472, surveyed June/July 1962 (DCSO records Vol. 32 Page(s) 13258-59)

The 1/4 sec. cor., determined from the remains of the original bearing trees:
A sawed Cedar stump 30" dia., bears S.41°E., 37 lks. dist., with a rotted face. (rec. S.42°E.)
A Cedar 32" dia., bears N.19°W., 51 lks. dist., with an open and chopped face. (Rec. N.18°W.)
At the corner point
Set an iron post, 30 ins. long, 2 1/2 ins. dia., 28 ins. in the ground, with brass cap marked
T 32 S R 5 W
1/4
S 6 | S 5
1962
from which
A Fir 6" dia., bears S.88°E., 38 1/2 lks. dist., mkd. 1/4 S5 BT
A Fir 10" dia., bears N.78°W., 54 lks. dist., mkd. 1/4 S6 BT

Survey by T.H. Mehl, III - For: Robert Dollar Co. - Oct. 1, 1968 - C.S. File 55/91

Found - GLO brass cap and iron pipe removed by logging operation.
Sawed Cedar stump 30", S.41°E., 37 lks.
Sawed Cedar stump 32", N.19°W., 51 lks.
6" Fir BT, S.88°E., 38 1/2 lks., good condition.
10" Fir BT, N.78°W., 54 lks., good condition but face covered by log pile.
Set 1" x 42" iron rod 36" in the ground.
Rescribed -
10" Fir above the log pile. The scribing reads "1/4 S, R.S. 749 BT".

continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

James McIntosh, Oregon Dept. of Forestry - 3/2006 - M150-23

Found - 1" iron rod (Mehl, 1968) (in place)
24" cedar (1901) S.42°E., 37 lks (now 24"x2½' high
rotted stump in place, axe work visible)
20" cedar (1901) N.18°W., 51 lks (now 33"x2' high
rotted stump in place, open and chopped face)
6" fir (1962) S.88°E., 38½ lks (missing)
10" fir (1962) N.78°W., 54 lks. Rescribed By T. H.
Mehl in 1968 (now 24" in place, upper and lower
faces closed, BLM BTT)
New - WP S.53°E., 3.70' to base
WP S.38°W., 3.80' to base
20" fir N.16°E., 34.7' to aluminum nail in BT face
scribed (¼S5BT) BTT