

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8604)

Set a granite stone 20x12x8 ins., 15" in the ground, for ¼ sec. cor., marked ¼ on W. face, from which
A Cedar 13" dia., bears S.11°E., 40 lks. mkd. ¼ S 4 BT.
A Fir 8" dia., bears N.88½°W., 18 lks. mkd. ¼ S 5 BT.

BLM dependent resurvey by Joseph S. Gawron and Norman J. McDonald, under Group #472, surveyed June/July 1962 (DCSO records Vol. 32 Page(s) 13250)

The ¼ sec. cor., determined from the remains of an original bearing tree:

A Fir snag 7" dia., bears N.88½°W., 18 lks. mkd. ¼ S5 BT.
At the Corner point
Set an iron post, 30 ins. long, 2 1/2 ins. dia., 26 ins. in the ground, with brass cap marked

T 32 S R 5 W
 ¼
 S 5 | S 4
 1962

from which

A Fir 17" dia., bears N.18°E., 88½ lks. mkd. ¼ S4 BT.
A Fir 22" dia., bears N.65°W., 84 lks. mkd. ¼ S5 BT.

Survey by Howard Johnstone, L.S. #498 - For: Roseburg Lumber Co. - March 13, 1985 - C.S. File 58/296-2

Found - 1962 Cadastral brass cap on iron pipe, OK.
8" Fir N.88½°W., 11.9 ft. OBT, rotten snag, scribe visible.
22" Fir N.65°W., 55.4 ft., resurvey BT, stump.
17" W.Fir N.18°E., 58.4 ft., resurvey BT, good scar.
New BT - 10" W.Fir S.76°W., 17.0 ft., scribed ¼ S5 BT.
Corner is 150 ft. West of road running N and S.