

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 302100

PRIMARY CORNER DESCRIPTION A.P. #2 - So. Bdy. Sec. 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8549)

-----  
Set post cor. of secs. 32, 33, 4 and 5, from which  
An Alder 10" dia., bears S.52°E., 41 lks.  
An Alder 7" dia., bears S.53°W., 31 lks.  
An Alder 10" dia., bears N.62°W., 8 lks.  
An Alder 8" dia., bears N.82°E., 23 lks.

GL0 survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8988)

-----  
Intersect Tp. cor. determined by bearing trees as post was missing.  
Reestablished Tp. cor. to secs. 32 and 33 T32S R5W by setting a basaltic stone 12x10x5 ins., 8" in the ground marked with 4 notches on the E. and 2 notches on the W. edges, from which  
An Alder 8" dia., bears N.82°E., 23 lks. dist., mkd. T32S R5W S4 BT.  
An Alder 10" dia., bears N.62°W., 8 lks. dist., mkd. T32S R5W S32 BT.  
The NE and SW trees were missing, burnt up. Therefore I established a NE tree which is an  
Alder 7" dia., bears N.45°30'E., 24 lks. dist. mkd. T32S R5W S33 BT.

GL0 survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8599)

-----  
Intersect S. bdy. of the Tp., 142 lks. W. of cor. to secs. 32, 33, 4 and 5, which is a granite stone 10x12x3 ins. above ground, marked as described the surveyor general, from which  
An Alder 8" dia., bears N.82°E., 23 lks. mkd. T32S R5W S33 BT. (Old BT)  
An Alder 10" dia., bears S.6°E., 38 lks. mkd. T33S R5W S4 BT. (New BT)  
A Fir 50" dia., bears S.51°W., 72 lks. mkd. T33S R5W S5 BT. (New BT)  
An Alder 10" dia., bears N.62°W., 8 lks. mkd. T32S R5W S32 BT. (Old BT)  
I destroyed all marks, referring to secs. 32 and 33

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 302100

PRIMARY CORNER DESCRIPTION A.P. #2, So. Bdy. Sec. 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM remonumentation of corners by Lynn Roseberry, Cadastral surveyor, under Group #'s 936 and 1000, surveyed July 1977/April 1980 (DCSO records Vol. 42 Page(s) 16643)

-----  
The Ives and Hyde standard cor. of secs. 4, 5, 32 and 33, on the N. bdy. of the Tp., determined at record bearing and distance from the remains of a bearing tree mkd. by Thiel:

A Fir snag 80" dia., bears S.51°W., 72 lks. dist., with scribe marks T33S R5W S5 B visible on opened blaze.

This corner now becomes angle point No. 2 of secs. 4 and 33. At the corner point

Set an iron post 28" long, 2½" dia., 20" in the ground, in a mound of stone, 3 ft. base, to top, with brass cap marked:

AP 2  
T 32 S R 5 W  
S 33  
S 4  
T 33 S  
1980

from which new bearing trees

A W.Fir 14" dia., bears N.25¼°W., 27 lks. dist., mkd. AP2 S33 BT.

A Hemlock 14" dia., bears S.11½°W., 100½ lks. dist., mkd. AP2 S4 BT.

Corner is located 20 lks. East of Woodford Creek, 5 lks. wide, course N.

Found OK by M. Hull, Feb. 2004 - M144-18

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 3006; Surveyed April 2021/Nov. 2022 - (DCSO records Vol. 59 Page(s) 24114) (Added 9/10/2024)

-----  
Angle Point No. 2 bet. secs. 4 and 33, reported by Roseberry in 1977-80, monumented with an iron post, 2½" dia., firmly set, with top 6" below the surface of the ground, with brass cap (properly mkd) mkd.

from which the remains of BTs reported by Roseberry

A hemlock, 29" dia., bears S.11½°W., 66.3 ft., with a healed blaze.

A rotted fir snag, size indeterminate, bears S.51°W., 47.5 ft., with scribe marks 33S R5W visible on open blaze. (Original)

and a new bearing tree

A fir, 9" dia., bears N.34¼°W., 16.6 ft., mkd. AP2 S33 BT.

Continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 302100

PRIMARY CORNER DESCRIPTION A.P. #2 - So. Bdy. Sec. 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Each new BT has a 2½"x¼"magnetic nail (Mag Nail) driven at the base on right side center and each monument established or reestablished has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.

Gregg Neitsch - For: John Hancock Life Insurance Co - 12/2022  
- M181-58

-----  
Found - 1980 BLM brass cap  
62" dia., D.Fir stump, 15' height, visible scribing,  
S.55°45'W., 50.0'  
10" dia., W.Fir, visible scribing, N.33°55'W., 16.8'  
(Rec. N.25½°W., 27 lks)