

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8567)

Set ¼ sec. post, from which
A W.Oak 30" dia., bears S.50°E., 39 lks.
A Maple 15" dia., bears N.30°W., 184 lks.

George J. Wenderoth - 1955 - C.S. File 46/148

1" Iron pipe, from which
48" W.Oak S.50°E., 25.7 ft.
16" Pine N.71°16'E., 68.6 ft.

Douglas Co. Surveyors Office - John M. Powell, Joe Brady, crew - Sept. 7, 1967 - C.S. File 53/52-58

Found - 5/8" Iron rod at ¼ corner and reference monuments as follows:
Hub and tack S.21½°W., 66.6 ft. and sight on 3 trunk Ash.
Sight on 16" W.Oak, S.35°E., as noted.
Hub and tack on this line, however, not found.
Said corner falls at correct sta. of 194450 in St. Hwy. R/W.
New BT - 8" W.Oak S.44½°E., 85.5 ft. scribed ¼ S22 CS BT.
Power pole No. E2908, S.20°W., 41.2 ft., PK nail in base of pole.
Corner lies North of R/W fence, 32.0 ft.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - K. Reed, K. Mosley, crew - April 23, 1980 - C.S. File 61/6-34

Found - 5/8" punched iron rod set by OSHD in 1966 at point as determined by Wenderoth to be the ¼ cor. S21|S22 (1" iron pipe set by Wenderoth in 1955, was replaced with OSHD iron rod in 1966)
An 8" W.Oak now a 10", with well healed double blaze bears S.44½°E., 85.5 ft.
A Power pole #E2908 T 135 with PK nail at base bears S.20°W., 41.2 ft.
An unrecorded punched 5/8" iron rod bears N.23°W., 37.0 ft., said rod in centerline of Frontage Road.
New Accessories:
A 13" W.Oak scribed "¼ S22 CS BT" bears S.77°E., 88.5 ft.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 48" culvert bears S.76°E., 35.0 ft. measurement taken at top center of southerly end said culvert.
Corner located 32.0 ft. North of R/W fence.

Douglas Co. Surveyors Office - R.W. Smith, Party Chief, S.J. Flause, notekeeper - Sept. 17, 1985 - C.S. File 62/29-21

Found - A center punched 5/8" dia. iron rod firmly set and protruding approx. 3" from ground.
No evidence of Wenderoth's 1" I.P. found.
8" W.Oak now an 11" DBH W.Oak with a fully healed double blaze bears S.44½°E., 85.5 ft. as per rec.
A power pole marked COPCO E 2908 T 135 with a PK nail set near base bears S.20°W., 41.2 ft. as per rec.
Corner is approx. 32.0 ft. North of R/W fence.
An unrecorded 5/8" I.R. in centerline of Quines Creek Frontage Road (Co. Rd. #303) located by metal detector, now buried under seal-coat, bears N.23°W., 37.0 ft.
13" W.Oak now a 14" DBH W.Oak with a fully healed double blaze, bears S.77°E., 88.5 ft. as per rec.
No evidence of original bearing trees found. No evidence of bearing trees from Wenderoth found.
Partial copies of OSHD notes in C.S. File 53/52 suggest that OSHD referenced out the 1" iron pipe set as the ¼ corner by Wenderoth and then reestablished the ¼ cor. as a 5/8" iron rod. 1980 DCSO visit perpetuates this position and the survey filed in the DCSO as M 83-6 indicates that the monument agrees well with section corner 1/2 mile South.
New Bearing Object:
An unrecorded 1" dia. iron pipe, firmly set, protruding 8" from ground, bears N.89°E., 84.8 ft.
Monument is southwest of driveway entrance at 600 and 601 Quines Creek Frontage Road.

Fd. OK, Jan. 1991, M 112-23
Fd. ¾" IP 5/2021 by D Feigel M178-29