

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8568)

Set ¼ sec. post, from which
A W.Oak 2" dia., bears N.13°E., 85 lks.
A W.Oak 8" dia., bears S.30°W., 135 lks.

W. F. Briggs, Co. Surveyor - For: H.L. Wilson (Levens Estate) July 1900 - Vol. 2 Page 94

Set new post at ¼ corner as per original BT standing
W.Oak 10" dia., bears S.30°W., 135 lks.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8623)

The ¼ sec. cor., which is a B.Oak post, 3 ft. long, 3" sq., 1 ft. above ground, marked ¼ S22 on N. face and 27 on S. face; (set by Co. Surveyor) and witnessed as described by the surveyor general; I remarked all bearing trees. This post stands about 150 ft. above sec. cor. 22, 23, 26 and 27.

George J. Wenderoth - Jan. 1956 - C.S. File 42/88

1¼" Iron pipe, from which
8" Fir S.50°55'W., 18.7 ft.
10" Madrona, N.52°25'E., 29.0 ft.

Cor. OK, Aug. 1967, J.M.P., DCSO C.S. File 53/52-36

Douglas Co. Surveyors Office - S.J. Flause, Deputy - T. Plouff, S. Means, crew - April 23, 1980 - C.S. File 61/6-49

Found - 1¼" iron pipe firmly set and protruding 0.8 ft. from ground. Pipe is approx. 1 ft. West of a random fence line running East only from ¼ corner. Search for but find no evidence of orig. BT. An 8" now 18" D.Fir bears S.51°W., 18.7 ft. has healed single blaze, no scribing visible and is tagged with a BLM bearing tree tag. A 10" now a 20" Madrone bears N.52°E., 28.1 ft. (Rec. N.52°25'E. 29.0 ft.) has partially healed single blaze with scribe marks visible and is
(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

tagged with a BLM bearing tree tag which is marked S.52°W., 28 ft.
Because of no connection in record to orig. evidence, WE DO NOT SET a brass cap but only perpetuate the position of ¼ cor. as determined by Wenderoth in 1956, C.S. 42/88. Iron pipe is still firmly set, we do not disturb, but add a bearing tree as follows:
A 5" Madrone bears N.0°E., 14.0 ft. bark scribed "¼ S22 CS BT"
No suitable trees available in other quadrants.

BLM resurvey by Virgil L. Stanger, Cadastral Surveyor, under Group #1145, surveyed May/Aug. 1983 - (DCSO records Vol. 47 Page(s) 17886)

The Sec. cor., perpetuated and recorded by Wenderoth in 1956, from original evidence no longer in existence, and subsequently rehabilitated and recorded by the County Surveyor Office in 1980, monumented with an iron pipe, 1¼" dia., firmly set, projecting 10" above ground, from which bearing trees mkd. by Wenderoth:
A Madrone, 19" dia., bears N.52°E., 42½ lks. dist., with healed blaze.
A Fir 20" dia., bears S.50¼°W., 28½ lks. dist., with healed blaze.
and a bearing tree mkd. by County Surveyors Office:
A Madrone, 8" dia., bears N.1½°E., 21 lks. dist., with scribe marks ¼ S22 CS BT visible on bark.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 22 ins. in the ground, directly over iron pipe, with brass cap marked
T 32 S R 5 W
¼ S 22
S 27
1983
(From this point, the cor. of secs. 22, 23, 26 and 27, bears S.89°36'E., 40.38 chs. dist.)

Fd. ok by R. Wytcherly 5/2007 - M153-29