

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 34 & 35 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8548)

Set post cor. of secs. 2, 3, 34 and 35, from which
A Laurel 4" dia., bears N.36°W., 36 lks.
A Laurel 5" dia., bears N.42°E., 26 lks.
A Laurel 6" dia., bears S.40°E., 42 lks.
A Fir 4" dia., bears S.12°W., 17 lks.

GL0 resurvey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8969 and 8970)

After making diligent search for Tp cor. to secs. 34 and 35 T32S R5W, I fail to find any traces of the cor. Much of the timber having been destroyed by fires. Therefore, I proceed to establish cor. to secs. 34 and 35 in the following manner. Set a basaltic stone 12x10x8 ins., 8" in the ground marked with 2 notches on the E. and 4 notches on the W. edges, from which
A Fir 10" dia., bears N.23°30'E., 26 lks. dist., mkd. T32S R5W S35 BT.
A Fir 10" dia., bears S.41°E., 52 lks. dist., mkd. T33S R5W S2 BT.
A S.Pine 6" dia., bears N.51°W., 35 lks. dist., mkd. T32S R5W S34 BT.

GL0 survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8615-16 and 8617)

The cor. of secs. 34, 35, 2 and 3, I find to be a sandstone, 6x8 ins., x 3" above ground, properly marked and from which
A Fir 10" dia., bears N.23°E., 25 lks. mkd. T32S R5W S35 BT.
A Fir 10" dia., bears S.40°E., 52 lks. mkd. T33S R5W S2 BT.
A Fir 8" dia., bears N.50°W., 35 lks. mkd. T32S R5W S34 BT.
A Fir 45" dia., bears S.54°W., 70 lks. mkd. T33S R5W S3 BT.

These trees do not agree with the description furnished by the surveyor general. I think they were not made by the U.S. surveyor of the offset Meridian, but were made afterwards by the U.S. surveyor, running the closing line from the S. bet. Secs. 2 and 3. (Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 34 and 35 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

We chop into the Fir 45" dia., when we discover a second set of marks evidently made by the surveyor of the Meridian, thus confirming the location of the original cor.

Ben B. Irving, Co. Surveyor - Wit: N.E. Richardson; Frank Kruse - June 11, 1930 - C.S. File 37/23; Vol. 4 Page 9 and RM 1-11 (and "old" corner book, page 171)

Found - 8" x 10" x 4" above ground basaltic stone as described in Govt field notes.
Original BTs in good shape which I reblaze and mark, as follows:
A 10" Fir N.23°30'E., 26 lks.
A 10" Fir S.41°W., 52 lks.
A 6" S.Pine N.51°W., 35 lks.

Douglas Co. Surveyors Office - John M. Powell, Joe Brady, crew - August 1967 - C.S. File 53/52-23

Found - Corner stone 8x10x4, no markings.
10" now 14" Fir N.23½°E., 17.2 ft., shows good bark scribing, plus a good original face.
6" S.Pine now 10" snag, N.51°W., 23.1 ft. shows good scribing.
No trace of SW BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R 5 W (Per
S 34 | S 35 Fritz,
C C not a
T 33 S R 5 W CC)
1967

New BT - 10" D.Fir N.20°W., 24.0 ft. mkd. T32S R5W S34 CC
CS BT.

This corner was renewed by Irving in 1930 and he bark scribed NE orig. BT, which has a good face.
Corner lies on steep East side of hill.

Ronald Quimby - For: Plum Creek Timber Co. - July 2015 - M166-36

Found - 2½" 1967 DCSO Brass cap
22" fir N.23°E., 17.2' - visible bark scribes
17" fir N.20°W., 24.0' - healed scar
New BTs- 5" fir S.28°E., 5.0' scribed "S35 BT"
17" fir S.18°W., 15.4' scribed "T32S R5W S34 BT"

continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 34 & 35 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 3006; Surveyed April 2021/Nov. 2022 - (DCS0 records Vol. 59 Page(s) 24112-3)

The cor. of secs. 34 and 35 only, T32S R5W reported by Thiel in 1904; perpetuated by Irving, Douglas County Deputy Surveyor, in 1930; subsequently perpetuated by the Douglas County Surveyor's Office in 1967; and further perpetuated by Quimby, in 2015; monumented with an iron post, 1½" dia., firmly set, projecting 14" above the ground, with brass cap (properly) mkd.

from which a BT reported by Thiel and bark scribed by Irving
A fir, 24" dia., bears N.23°E., 16.5 ft., with a healed blaze and illegible scribe marks visible on bark.
and a BT mkd. by the Douglas County Surveyor's Office

A fir, 20" dia., bears N.20°W., 23.5 ft., with a healed blaze.

and bearing trees mkd. by Quimby

A fir, 7" dia., bears S.31¼°E., 4.9 ft., with illegible scribe marks visible on partially healed blaze.

A fir, 19" dia., bears S.16¼°W., 14.8 ft., with illegible scribe marks visible on partially healed blaze.