

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8583)

-----  
Set ¼ sec. post, from which  
A Pine 5" dia., bears N.30°W., 91 lks.  
A Laurel 5" dia., bears North, 92 lks.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8617)

-----  
The post is gone and only the NW bearing tree is standing. I replace the cor. by setting a Cedar post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S27 on W.; and 26 on E. face, from which  
A Fir 14" dia., bears North, 68 lks. dist. mkd. ¼ S26 BT.  
The other tree as described by the surveyor general.

George J. Wenderoth - Oct. 11, 1945 - C.S. File 43/24

-----  
Found both old BTs  
18" Pine N.30°W., 60.06 ft.  
20" Fir North 44.88 ft.  
Drove 1½" I.P. for corner.

Fd. OK, V. Tracy, DCSO, July 6, 1967, C.S. File 53/32-38

Douglas Co. Surveyors Office - Gary E. Commons, P. Earle, crew - March 19, 1975 - C.S. File 57/21-3

-----  
Found - 1½" x 36" I.P. buried 30" in ground.  
18" Pine now 30", N.30°W., 60.06 ft. Tree has been opened in past, now nearly rehealed. No scribe visible.  
20" Fir now 28", North, 44.88 ft. Scar plainly visible.

Set Brass cap on 1½" x 30" I.Pipe 28" in ground mkd:

County Surveyors Office

T 32 S

¼

S27 | S26

R 5 W

1975

We placed old 1½" x 36" I.P. 30" in ground beside brass cap.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause, crew - April 20, 1989 - C.S. File 62/63-13

-----  
(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Found - 1975 DCSO 2½" dia. brass cap on a 1¼" O.D. iron pipe, protruding 2" above ground.  
A 1" I.D. iron pipe protruding 10" above ground, bears South 0.5 ft. from DCSO BC/IP.  
5" now 29" dia. P.Pine with a partially healed single blaze, no scribing visible, bears N.30°W., 60.1 ft. (Orig.) (agrees w/rec.)  
14" now 30" D.Fir with a fully healed double blaze bears North 44.9 ft. (agrees w/rec) (1901 GLO survey)  
New BTs -6" D.Fir double blazed and scribed ¼ S26 CS BT, bears S.36½°E., 13.7 ft.  
15" D.Fir double blazed and scribed ¼ S27 CS BT bears S.19½°W., 19.0 ft.

Fd. OK, by R. Templin, Feb. 1994, M 120-35  
Fd. ok by R. Wytcherly 5/2007 - M153-29  
Fd. BC per rec by R. Brown 2/2018 - M171-40  
Fd. BC per rec by R. Brown 7/2019 - M171-65