

PRIMARY CORNER DESCRIPTION Sec Cor for 22, 23, 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8563)

Set post, cor. to secs. 22, 23, 26 and 27, from which
A Cedar 14" dia., bears S.75°E., 42 lks.
A Cedar 15" dia., bears N.65°W., 42 lks.
A Cedar 11" dia., bears S.50°W., 55 lks.
A Fir 8" dia., bears N.30°E., 28 lks.

W. F. Briggs, Co. Surveyor - For: H.L. Wilson (Levens Bros. Estate) July 1900 - Vol. 2 Page 94-95 and Page 98

Set new Yew post marked, as per original BT.

Fd. and used by O.F. Thiel, Contract #729, Dec. 24, 1900 and Sept 12, 1901 (DCSO records, Vol. 20 Page 8618)

George J. Wenderoth - 1953, M 5-28; - June 1957, C.S. file 45/154

1/2" Iron pipe. (in road)
18" Fir N.30°E., 18.5 ft.
20" Cedar N.81°15'E., 93.8 ft.
11" Cedar S.43°45'E., 126.0 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, Crew - August, 1967 - C.S. File 53/52-1

Found - 1/2" Iron pipe approx. 2" underground.
Orig. 8" D.Fir N.30°E., 18.5 ft., tree has been opened, "S" visible.
20" Cedar N.72°E., (Rec. N.81°15'E.) 93.8 ft., shows good scar.
11" Cedar now down, in creek.

Set Brass cap at cor. mkd: County Surveyors Office

T 32 S R 5 W
S 22 | S 23
S 27 | S 26
1967

New BTs -12" Cedar N.80°W., 208.7 ft. mkd. T32S R5W S22 CS BT
6" double Cedar S.57°E., 86.0 ft. mkd. T32S R5W S26 CS BT.

No good trees in SW quad.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec Cor for 22, 23, 26 and 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - Gary Commons, Peter Earle, crew - March 16, 1975 - C.S. File 57/21-2

Found - 1967 DCSO brass cap on top of ground.
Orig. 8" D.Fir now 21", N.30°E., 18.5 ft. with healed scar.
20" Cedar now 26", N.72°E., (Rec. N.81°15'E.) 93.8 ft. with well healed scar.
6" double Cedar now 8", S.57°E., 86.0 ft. scribe T32S R5W S26 CS BT visible.
12" Cedar now 18", N.80°W., 208.7 ft. scribe T32S R5W S22 visible.
We also find 1/2" I.Pipe buried 1 ft. under the surface.

Reset Brass cap 26" in ground and placed 1/2" I.P. alongside, buried 1 ft.

We placed witness post 1 ft. to South of cap.

This corner is on outside (East) of slight right hand corner across road from large barn.

Cor. Fd. and used in BLM survey by V.L. Stringer, under Group #1145, surveyed May/Aug. 1983 (DCSO records, Vol. 47 Pages 17876-77)

Found OK by D. Edwards, Oct. 2003 - M143-13

Fd. ok by R. Wytcherly 5/2007 - M153-29