

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Oscar F. Thiel, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8593)

Set a fir post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 S35 on W. face and 36 on E. face, from which

A Yew 6" dia., bears N.42°E., 21 lks. mkd. 1/4 S36 BT.

A Fir 20" dia., bears S.6°W., 22 lks. mkd. 1/4 S35 BT.

This cor. stands 175 ft. below top of ridge.

George J. Wenderoth - C.S. File 45/54 - 1952

1 1/2" I.P.

12" Yew N.42°E., 13.8 ft.

20" Fir S.86°W., 41.2 ft.

Douglas Co. Surveyors Office - John Powell and Joe Brady - Aug. 1967 - C.S. File 53/52-25

Found - 1" Iron pipe at corner.

6" Yew now 10" N.42°E., 13.9 ft. scribe visible "1/4 S36."

20" D.Fir S.6°W., 14.5 ft., now out and covered with log deck.

Set Brass cap at cor. mkd: County Surveyors Office

T 32 S R 5 W

1/4 S 35 | S 36

1967

New BTs -15" D.Fir N.68°E., 60.0 ft. mkd. 1/4 S36 CS BT.

24" D.Fir S.57°W., 57.4 ft. mkd. 1/4 S35 CS BT.

This corner lies under log on East edge of old log deck.

Douglas Co. Surveyors Office - M. Lenora Ladig and P.L. Earle, crew - April 8, 1976 - C.S. File 59/8-14

Found - 1 1/2" I.Pipe at corner and laying alongside I.P., a 1 1/2" x 28" I.P. with 1967 DCSO brass cap.

An orig. 6" now 9" Yew bears N.42°E., 13.9 ft. with "1/4 S36" visible in good blaze. Tree is alive (BT is leaning to the NE., dist. and bearing taken from base of tree)

15" now 19" D.Fir bears N.68°E., 60.0 ft. with three blazes. "S3" visible in upper blaze. Middle blaze well healed and "B" visible in lower blaze.

No trace of other BTs.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

This corner lies on the East edge of old log deck. Found a 48" log resting on a 30" log, 2 ft. over the I.P. making corner unaccessible. Cut away logs, corner is now accessible.

Set at true corner point, the 1967 DCSO brass cap stamped "1976" above 1967 at bottom of cap.

1½" I.P. on East side of cap.

New BT - A 6" W. Fir bears S.70°E., 13.7 ft. scribed "¼ S36 CS BT" in double blaze.

No suitable trees to the West.

J. McIntosh, survey for State of Oregon Dept. of Forestry
May 2000 - M135-1

Found OK as above, rewitnessed:

Set- orange carsonite markers cbm-250 labeled witness post
bears, N.50°W., 4.2 ft. to base.

bears, N.36°E., 4.2 ft. to base.

16" Fir, bears S.48°W., 17.5 ft. to aluminum nail in BT
face, scribed 1/4 S35 BT