

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8582)

-----  
Set ¼ sec. post, from which  
A burned Fir 20" dia., bears South, 20 lks.  
A Fir 30" dia., bears N.85°W., 75 lks.

-----  
GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8624)

-----  
Set temp. ¼ sec. cor. The old cor. and bearing trees have been destroyed by fire.

-----  
Survey by Richard L. Templin Jr. - For Sierra Land Co. - April 30, 1956 - C.S. File 42/133

-----  
Found - 50" Fir with bark scribe, N.85°W., 75 lks.  
Rotted stump 30" Fir, South, 20 lks.  
Set rock, 3" x 8" x 14", mkd. ¼ N. face.  
Scribed -12" Fir S.15°10'W., 44.7 ft. mkd. ¼ S25 RE 3024 BT.  
50" orig. Fir BT on NE root collar mkd. "¼ S24 BT".

-----  
Gerald Nygren, surveyed for Silver Butte Timber Co. and Seneca Jones Timber Co. Aug. 1998 - M130-34

-----  
Found - 3" x 8" x 14" rock marked 1/4, and bearing trees.  
Set - 5/8" x 30" iron rod w/yellow plastic cap marked "NYGREN LS1035", and set rock alongside.

-----  
Fd 5/8" IR & accessories per previous renewal by K. DeGroot, 10/14/2005 - M148-56  
Fd. as per M130-34, D.Edwards 4/2008 M155-51