

PRIMARY CORNER DESCRIPTION Angle Point, E. Bdy, Sec. 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8454)

-----  
Set post corner of secs. 30, 31, 25 and 36, from which  
A Fir 8" dia., bears S.25°W., 18 lks.  
A Fir 12" dia., bears S.50°E., 73 lks.  
A Fir 6" dia., bears N.66°E., 43 lks.  
A Hemlock 12' dia., bears N.40°W., 20 lks.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8474)

-----  
At corner of secs. 30, 31, 25 and 36, which is a post 4" sq., 24" above ground, marked and witnessed as described by the surveyor general. I reestablish this corner as follows, at same point  
Set a Fir post 3 ft. long, 4" sq., 24" in the ground, for corner of secs. 25 and 36, T32S R5W., marked: T32S S36 on SW.; and R5W S25 on NW. faces; with 1 notch on S. and 5 notches on N. edges; from which  
A Fir 10" dia., bears S.25°W., 18 lks. dist., marked T32S R5W S36 BT.  
A Hemlock 16" dia., bears N.40°W., 20 lks. dist., marked T32S R5W S25 BT.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8590-91)

-----  
Intersect E. bdy. of Tp. 159 lks. N. of cor. of secs. 25, 30, 31 and 36, which is gone; I reestablish the cor. by setting a Hemlock post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 25, 30, 31 and 36, marked T32S S30 on NE.; R4W S31 on SE.; S36 on SW.; and R5W S25 on NW. faces, with 5 notches on N. and 1 notch on S. edges, from which  
A Fir 24" dia., bears N.22°E., 86 lks. mkd. T32S R4W S30 BT. (New BT.)  
A Fir 40" dia., bears S.83°E., 12 lks. mkd. T32S R4W S31 BT. (New BT)  
A Fir 8" dia., bears S.25°W., 18 lks. mkd. T32S R5W S36 BT. (Old BT)  
A Hemlock 12" dia., bears N.40°W., 20 lks. mkd. T32S R5W S25 BT. (Old BT)  
I destroyed all marks referring to secs. 25 and 36.

(Cont. Next Page)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Survey by Arnold Gibson, Oregon State Board of Forestry -  
Wit: Lloyd D. Smith - May 30, 1972 - C.S. File 55/233-16

-----  
(Original corner 30, 31, 25 and 36)  
Original post missing, from which  
8" Fir bears S.25°W., 18 lks., missing  
12" Fir bears S.50°E., 73 lks. missing (destroyed by  
Nicklin, 1896), root holes in place.  
6" Fir bears N.66°E., 43 lks.; missing (destroyed by  
Nicklin, 1896), covered by fresh logging slash.  
12" Hemlock bears N.40°W., 20 lks., missing.  
1896 post, missing, by Nicklin.  
1900 Hemlock post, missing, by Thiel, from which a  
24" Fir bears N.22°E., 86 lks.; now 16" x 10 ft. rotten  
stub, in place, no face.  
40" Fir bears S.83°E., 12 lks.; now 46" windfall snag,  
found back cast B and scribes SW.  
17" W.Fir (not recorded) bears N.56°W., 54.0 ft.; face  
opened, scribes T32S R5W S visible at 50 years.  
Set 1½" x 36" galv. iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY AP T32S S36 T32S S31 R4W 1972  
RS 359" in ground, and from which  
11" Fir bears N.44°E., 15.2 ft. to face, scribed T32S R4W  
S31 AP BT.  
10" Fir bears N.80°W., 20.1 ft. to face, scribed T32S R5W  
S36 AP BT.  
Set 4" x 4" x 72" white painted Cedar post, 2.5 ft. S.44°E.,  
of corner pipe. Oregon State Forestry Dept. metal location  
post on 11" Fir N.44°E., 15.2 ft. Also poster on 10" Fir  
N.80°W., 20.1 ft.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under  
Group #977 Surveyed, May/June 1979 - (DCSO records Vol. 43  
Page(s) 16762)

-----  
CORNER REPORT ONLY

Beginning at the cor. of secs. 25, 30, 31 and 36, on the E.  
bdy. of Tp., established by Ives and Hyde in 1854, changed to  
a cor. of minimum control by Chapman and Nicklin, in 1897,  
and subsequently changed to an angle point by Thiel, in 1901,  
perpetuated and recorded by Arnold Gibson, #359, in 1972,  
monumented with a galv. iron pipe, 1½" dia., firmly set,  
projecting 3" above ground, with bronze cap mkd.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 700178

PRIMARY CORNER DESCRIPTION AP, E. bdy. Sec. 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

OREGON STATE BOARD OF FORESTRY

T32S AP T32S

S36 | S31

R5W | R4W

1972

RS 359

from which the remains of bearing trees mkd. by Thiel

A decayed Fir stump 24" dia., bears N.18°E., 88 lks. dist.,  
no marks remaining. (Rec. N.22°E., 86 lks.)

A roothole bears S.83°E., 15 lks. dist., alongside of  
which is lying a decayed Fir, 40" dia., no marks  
remaining. (Rec. 12 lks.)

and the remains of a bearing tree recorded by Gibson

A rotted White Fir stump 17" dia., bears N.56°W., 82 lks.  
dist., with scribe marks S5S visible on decayed portion  
of blaze.

and bearing trees mkd. by Gibson

A Fir 12" dia., bears N.37½°E., 23½ lks. dist., with  
scribe marks T32S R4W visible on partially healed  
blaze.

A Fir 12" dia., bears N.81¼°W., 30½ lks. dist., with  
healed blaze.