

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 24; and 19 of T32-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8453)

Set 1/4 sec. post, from which
A Fir 18" dia., bears S.73°W., 43 lks.
A Fir 6" dia., bears S.35°E., 8 lks.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #977 Surveyed, May/June 1979 - (DCSO records Vol. 43 Page(s) 16766-67)

The 1/4 sec. cor., determined at record bearing and distance from the remains of the original bearing trees
A root hole bears S.35°E., 8 lks. dist., with a down Fir alongside, 36" dia., with healed blaze.
A root hole bears S.73°W., 43 lks. dist. with a down Fir alongside, 48" dia., with scribe marks 1/4 S BT visible on opened double blaze.

At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S
R 5 W R 4 W
1/4
S 24 | S 19
1979

from which new bearing trees
A Fir 12" dia., bears N.70°E., 41 lks. dist. mkd. 1/4 S19 BT.
A Fir 7" dia., bears N.61°W., 59 lks. dist. mkd. 1/4 S24 BT.

Fd. OK by Nygren, Aug. 1998 - M130-34

Fd USBLM BCIP & accessories per previous renewal by K. DeGroot, 10/14/2005 - M148-56