

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13; & 7 & 18, T32-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8452)

Set post corner of secs. 7, 18, 12 and 13, from which
A Fir 18" dia., bears N.48°W., 94 lks.
A Fir 16" dia., bears N.51°E., 7 lks.
A Fir 14" dia., bears S.46°E., 17 lks.
A Hemlock 14" dia., bears S.70°W., 34 lks.

Survey by G.G. Stewart, Deputy Co. Surveyor - May, 1922 - Vol. 3 Page 121; M 3-32 and C.S. File 45/186

Set an Iron bar from 2 O.B.T. stumps. Others gone.
Marked - 24" Fir N.16°E., 183.2 ft.
30" Fir N.71°E., 216.0 ft.
No other trees available.

Survey by George Wenderoth - 1953 - C.S. File 45/136 and M 3-9 (Also C.S. Files 39/158 and 39/159)

Set 1/2" x 36" Iron pipe, from which
10" Fir S.60°35'E., 60.3 ft.
9" Live Oak N.4°06'E., 105.8 ft.
Found stump of old bearing tree scribed. Other tree scribe marks burned off.

Corner OK, DCSO, John Powell, August 1967 C.S. 53/52-50

Douglas Co. Surveyors Office - John M. Powell and crew - July 18, 1969 - C.S. File 54/114-30

Found - 1/2" I.Pipe at corner.
9" now 13" Live Oak N.4°E., 105.8 ft., shows good scar. (This tree to be cut down)
10" now 22" Fir S.60½°E., 60.3 ft. shows good scar.
New BT - 6" D.Fir N.2°E., 87.5 ft. mkd. T32S R4W S7 CS BT.
B.O. - Power pole N.21½°W., 24.0 ft., Pole No. E3457 (ABA10)

BLM resurvey by Larry D. Evans, Cadastral Surveyor, under Group #736, surveyed May/June 1971 (DCSO records Vol. 37 Page(s) 15328-29)

The Sec. cor., perpetuated and recorded by Stewart in 1922, from two of the remaining original 1854 bearing trees which are no longer in existence; subsequently perpetuated and
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 12 & 13; 7 & 18, T32-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

recorded by Wenderoth in 1944, from 2 bearing trees mkd. by Stewart in 1922, monumented with an iron rod, 38" long, 1½" dia., firmly set, 46" in the ground, (Cont. Next Page)

from which the remains of the bearing trees mkd. by Stewart:

A burned and decayed Fir stump, 33" dia., bears N.16°E., 279 lks. dist., no marks visible.

A burned and decayed Fir stump, size indeterminate, bears N.71°E., 329 lks. dist., no marks visible.

and bearing trees mkd. by Wenderoth:

A sawed Live Oak stump 15" dia., bears N.4¼°E., 160½ lks. dist., with healed double blaze.

A Fir 25" dia., bears S.60½°E., 91 lks. dist., with healed double blaze.

and a bearing tree and bearing object mkd. by the County in 1966:

A Fir 8" dia., bears N.2°E., 132½ lks. dist., with illegible scribe marks visible on partially healed and pitched over blaze.

A Power pole No. E3457, bears N.21½°W., 36½ lks. dist.

At the Corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 36 ins. in the ground, with brass cap marked

	T	32	S
R	5	W	R 4 W
	S	12	S 7
	S	13	S 18
			1971

Deposit iron rod alongside iron post.

DCSO corner report by L.E. Monrean, C.S. File 62/16-21, found 2" bar (BLM reference 1½") Did not find ½" I.P. - March 1984

Fd. OK, 2" I.R., by Raymond Brown, July 1993, M 117-58

Found OK by D. Edwards, July 2002 - 2002-0032

Found OK by D. Beedle, Mar. 2004 - M144-3

FD. Ok by D Edwards, Aug. 2006 - M151-50

Fd. OK by R. Wytcherley, April 2008 - M155-53

Kristian DeGroot - For: Silver Butte Timber Co. - 10/2010 - M157-32

LAT: 42°47'49.137266" N. LONG: 123°13'42.458742" W.

Found a 1971 USBLM BCIP by Larry Evans, buried 1.2 ft below the west shoulder of private rocked driveway. The 2" iron bar bears N.30°E., 0.35 ft, & 0.25 ft above top of BCIP. monument and accessories per 1971 BLM record.