

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 038030

PRIMARY CORNER DESCRIPTION SW Cor. Redfield DLC 38, Sec. 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

DLC Survey by J.A. Burnett, under Contract #75 dated Nov. 22, 1856 (DCSO DLC records Pg. 686)

Set a Post, from which
A Maple 6" dia., bears N.17.30E. 47 lks.

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, Group No. 2125, surveyed July 2006/Feb. 2007 - (DCSO records Vol. 55 Page(s) 21444)

Point for the SW. cor. of DLC No. 38 at proportionate position, determined by the Grant Boundary method of adjustment, between the original Northwest cor. of DLC 38 and the reestablished Southeast corner of DLC No. 38, there is no remaining evidence of the original corner.

Set a stainless steel post, 28" long, 2½" dia., 28" in the ground, with brass cap mkd. T 32 S R 6 W

DLC 38
S 34
2007

from which

A utility pol, No. PPL E1683, bears N.5°E., 457.7 ft.

A utility pole, No. PPL E1681, bears N.68½°W., 444.9 ft.
Deposit a magnet in a white plastic case at the base of the stainless steel post.