

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T32-7

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8631)

Set post, cor. to secs. 31, 36, 25 and 30, from which
A Fir 4" dia., bears S.57°W., 39 lks. dist.
A Fir 30" dia., bears N.24°W., 17 lks. dist.
A Fir 40" dia., bears N.51°E., 17 lks. dist.
A Fir 30" dia., bears S.52°E., 14 lks. dist.

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8657-58) and Page 8714)

Found old cor. and witness tree standing, viz:
A Fir 40" dia., bears N.51°E., 17 lks. dist. marked T32S R6W S30 BT.
A Fir 36" dia., bears S.52°E., 14 lks. dist., marked T32S R6W S31 BT.
A Fir 8" dia., bears S.57°W., 39 lks. dist..
Did not open old blazes.
A Fir 36" dia., bears N.24°W., 17 lks. dist. marked T32S R7W S25 BT.
The sec.on E. having been surveyed, I did not remove old cor.

George J. Wenderoth - L.S. #5 - August 1945 (no record source found for this renewal. Infor. from old renewal #8)

Set 3/4" Iron pipe.
Found the 4 original witness trees:
4" Fir S.57°W., 25.47 ft., dead and scribe rotted away.
30" Fir N.24°W., 11.22 ft., scribe marks very plain.
40" Fir N.51°E., 11.22 ft. scribe marks badly burnt.
30" Fir S.52°E., 9.24 ft. Tree lying on ground.
Marked the following new bearing trees:
12" Fir S.64°08'W., 38.0 ft.
8" Alder S.64°30'E., 84.9 ft.

Survey by T.H. Mehl, III - For: Robert Dollar Co. - May 10, 1967 - C.S. File 55/15-3

Found - 3/4" I.P. by Wenderoth.
16" Alder S.64°30'E., 84.9 ft. by Wenderoth.
Stump of 36" Fir, N.24°W., 17 lks.
Bug killed 48" Fir, S.52°E., 14 lks.
4" Fir, S.57°W., 39 lks., destroyed by road construction.

(Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T32-7

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

A Fir 30" dia., bears N.82¼°W., 158 lks. dist., mkd. T32S
R7W S25 BT.
Reset iron pipe alongside iron post.

Fd. Ok by Gerald Nygren, 10/96, M 125-75
Fd. OK by K. Hoffine, Jan. 2002 - M139-33