

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13 of T32-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8633)

Set ¼ sec. post on steep N. slope, from which
A Fir 20" dia., bears N.57°E., 58 lks. dist.
A Fir 18" dia., bears S.82°W., 34 lks. dist.

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1861 (DCSO records Vol. 20 Page(s) 8660)

Set Cedar post, 4 ft. long, 4" sq., mkd. ¼ S on W. side, 18" in ground for the ¼ sec. cor., from which
A Fir 24" dia., bears S.22°E., 50 lks. dist. mkd. ¼ S BT.
A Fir 30" dia., bears S.35°W., 37 lks. dist. mkd. ¼ S BT.

Not Fd. by John Powell, DCSO 10/1967 (added 3/28/2017) C.S. File 54/53-20 - No trace of BTs good line & paced in calls from north & south. Face on one tree opened 34 yrs old. Nothing on this tree.

BLM resurvey by G. Steven Popken, Cadastral Surveyor & James J. Carlson, under Group #884. Surveyed Sept. 1975/June 1976 (DCSO records Vol. 37 Page(s) 15314)

Point for the ¼ sec. cor. at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S
1/4
R 7 W | R 6 W
S 13 | S 18
1976

from which
A Fir 13" dia., bears N.55°E., 17½ lks. mkd. ¼ S18 BT.
A Fir 10" dia., bears S.65°W., 48 lks. mkd. ¼ S13 BT.

BLM Resurvey by Lynn Roseberry Cadastral Surveyor under Group #884 - Surveyed June 1979 (DCSO records Vol. 41 Pg) 16236)

Point for the ¼ sec. cor. of secs. 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.
From this point, the ¼ sec. cor. of secs.13 and 18, erroneously reestablished by Popken and Carlson in 1976, bears S.3°21'W., 0.18 chs., monumented with an iron post 2½" dia., firmly set, projecting 4" above ground, mkd. and witnessed as described in the official record of the 1975-76 resurvey.
(Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13 of T32-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

I remove the iron post, and at the true corner point
Reset the iron post, 28" long, 2½" dia., 24" in the ground,
with brass cap mkd. T 32 S

¼
R 7 W | R 6 W
S 13 | S 18
1976
1979

from which bearing trees mkd. by Popken and Carlson

A Fir 15" dia., bears S.58½°E., 15½ lks. dist., with
scribe marks ¼ S18 BT visible on partially healed
blaze.

A Fir 12" dia., bears S.49°W., 58 lks. dist., with scribe
marks ¼ S13 BT visible on partially healed blaze.

BLM resurvey by Mark Dixon and Henry Hartley, Cadastral
Surveyors, under Group #1337, surveyed July/Sept. 1989 (DCSO
records Vol. 48 Page(s) 18561)

Point for the ¼ sec. cor. of secs. 13 and 18, at
proportionate distance; there is no remaining evidence of the
original corner.

From this point, the ¼ sec. cor. of secs. 13 and 18,
erroneously corrected by Roseberry in 1979, bears
N.16°33'30"E., 0.485 chs. dist., set, marked, and witnessed
as described in the official record. Remove the iron post
and at the true corner point

Reset the iron post, 28" long, 2½" dia., 24" in the ground
with brass cap mkd. T 32 S

¼
R 7 W | R 6 W
S 13 | S 18
1976
1979
1989

from which bearing trees mkd. by Popken and Carlson, and
re-described by Roseberry

A Fir 16" dia., bears N.35°E., 47 lks. with healed blaze.

A Fir 13" dia., bears N.75 3/4°W., 30½ lks., with healed
blaze.