

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 203100

PRIMARY CORNER DESCRIPTION No. Sec. cor. for 5 & 6 only, T33-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8638)

-----  
Set post, cor. to secs. 5 and 6, T33S R6W, from which  
A Laurel 8" dia., bears S.46°W., 63 lks. dist.  
A Fir 13" dia., bears S.68°E., 78 lks. dist.

W.H. Byars, under contract # 431, dated March 29, 1882 (DCSO records Vol. 21 Page(s) 9023-24)

-----  
Intersect North boundary of Township 265 lks. East of corner to Secs. 31 and 32, T32S R6W.  
Set a Fir post, 4 ft. long, 4" sq., 20" in the ground, marked T32S R6W S32 on NE face, T33S R6W S5 on SE face, and S6 on SW face, also 5 notches on East and one notch on West angles of same, for the corner to Secs. 5 and 6, from which  
A Fir 20" dia., bears N.1°E., 53 lks. mkd. T32S R6W S32 BT.  
A Fir 14" dia., bears S.13°E., 41 lks. dist. mkd. T33S R6W S5 BT.  
A Fir 16" dia., bears S.28°W., 29 lks. dist. mkd. T33S R6W S6 BT.

Wallace Owen - For: Robert Dollar Co. - April 18, 1958 - C.S. File 42/354

-----  
Found - Corner in poor condition, from which  
Orig. 8" Laurel S.46°W., 63 lks., now missing  
13" Fir bears S.68°E., 78 lks., now a rotten stump  
Set the corner from the Fir, using compass and chain.  
Drove a 1" iron rod and scribed:  
A 12" Fir S.23°30'E., 38.8 ft. "S5 RS 424 BT".  
42" Fir S.51°W., 62.8 ft. "S6 RS 424 BT".

Fd. OK, R. Thompson, April 1984, RM 3-61

Fd. OK, August 1990, M 112-14

Douglas County Surveyors Office - Randall Smith & Stephen Flause - 9-21-93 - C.S. 64/66 - 7

-----  
Accessories Fd. -  
34" dia. 2' high rotted D.Fir stump, no blazes or scribing, bears N.1°E., 35.8' Orig. BT.  
20" dia. 2½' high rotted D.Fir stump, scribing found "BT", bears S.13°E., 27.7' Orig. BT.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION No. Sec. cor. for 5 & 6 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

24" dia. 2½' high rotted D.Fir stump, scribing found "BT" facing northwest, no blazes or scribing found on northeast face, bears S.28°W., 19.5' Orig. BT.

Note: this stump is an orig. BT to Hype & Gardner 1855 North township line of T33S (13" fir, S.68°E., 78 lks.)

Monument Set -

2 3/8" dia. DCSO Brass Cap on a 1 3/8" by 32" long iron pipe is set from orig. Brg's & Face distances to orig. BT's. BC/IP protrudes 8" above ground.

1" dia. Iron bar protruding 4" above ground, bears N.88 3/4°W., 57.1' from BC/IP (iron bar from Wallace Iron)

New Accessories -

7" dia. Madrone bark scribed "T33S R6W S5 CS BT", bears S.59½°E., 23.9', to center of root crown.

9" dia. D.Fir, double blazed and scribed "T33S R6W S6 CS BT", bears S.46½°E., 6.6'.

10" dia. D.Fir, double blazed and scribed "T33S R6W S6 CS BT", bears S.31½°W., 14.4'.

7" dia. D.Fir, double blazed and scribed "T33S R6W S6 CS BT", bears S.79½°W., 4.9'.

C.S. File 64/66-8 - 9/15/1993

NOTE: Corner set by Wallace Owen for Robert Dollar Co. in 1958, that has been used as the sec. corner for 5 & 6 only, bears S.88 3/4°E., 57.1'

Monument FD. At that corner -

1" dia. iron bar protruding 4" above ground

Accessories Fd. -

24" dia. 2½' high rotted D.Fir stump, with partial scribing found "BT", bears S.68°E., 51.5' Orig. BT

48" dia. down D.Fir fell on face, found near record BRG. & Dist. (S51°W., 62.8')

22" dia. D.Fir with a fully healed double blaze, bears S.23½°E., 38.8'.

New Accessories -

9" dia. D.Fir, double blazed & scribed "X CS BT", bears S.33½°E., 3'.

9" dia. D.Fir, double blazed & scribed "X CS BT", bears S.26°W., 11'.

7" dia., D.Fir, double blazed & scribed "X CS BT", bears N.70°E., 14.2'.

See C.S. 64/66-8