

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 20

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8692)

A Fir tree 18" dia., which I marked  $\frac{1}{4}$  S. on N. face, for the  $\frac{1}{4}$  sec. cor., from which

A Fir 14" dia., bears S.30°E., 22 lks. dist., mkd.  $\frac{1}{4}$  S BT.

A Pine 12" dia., bears N.10°W., 26 lks. dist., mkd.  $\frac{1}{4}$  S BT.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #910 Surveyed, Aug/Sept. 1976 - (DCSO records Vol. 41 Page(s) 16324)

The  $\frac{1}{4}$  sec. cor., monumented with the remains of the original corner tree, a sawed and decayed Fir stump, 24" dia., no marks visible, from which the remains of the original bearing trees:

A decayed Fir snag, size indeterminate, bears S.30°E., 22 lks. dist., with chaining notch visible on decayed blaze.

A root hole bears N.10°W., 26 lks. dist., with a down and decayed Ponderosa Pine alongside, size indeterminate, with illegible scribe marks visible on opened double blaze.

At the corner point

Remove the decayed Fir stump and set an iron post, 28" long, 2 $\frac{1}{2}$ " dia., 24" in the ground, with brass cap mkd.

T 32 S R 6 W

$\frac{1}{4}$   $\frac{S 17}{S 20}$

1976

from which new bearing trees

A Fir 8" dia., bears N.51°W., 15 lks. dist., mkd.  $\frac{1}{4}$  S17 BT.

A Fir 7" dia., bears S.47  $\frac{3}{4}$ °E., 20 $\frac{1}{2}$  lks. dist., mkd.  $\frac{1}{4}$  S20 BT.