

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 243100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 5 only, T33-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8638)

Set ¼ sec. post on N. slope of mountain, from which
A Red Fir 18" dia., bears S.25°E., 10 lks. dist.
A Chinquapin 5" dia., bears S.85°W., 13 lks. dist.

G.J. Wenderoth - N.E. Richardson - April 1942 - C.S. File 16/55 and M 22-50

1/2" Eye bolt already set in ground.
Found stump of original BT, S.25°E., 6.9 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Sept/Oct. 1967 - C.S. File 54/53-10

Found - 1/2" Eye bolt at ¼ corner.
Orig. 18" Fir, now stump with rotten face, bears S.25°E., 6.6 ft.
New BTs -10" D.Fir S.27°E., 13.2 ft. mkd. ¼ S5 CS BT.
14" D.Fir S.52°W., 14.3 ft. mkd. ¼ S5 CS BT.
This corner lies 198.0 ft. East of ¼ cor. Sec. 32 only.

Fd. OK, by R. Thompson, April 1984, RM 3-61

Fd. OK, August 1990, M 112-14