

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8653)

Set ¼ sec. post and leave prairie, from which
A B.Oak 6" dia., bears N.10°W., 191 lks. dist.
A W.Oak 7" dia., bears S.15°W., 71 lks. dist.

George J. Wenderoth, L.S. #5 - Aug. 1945 (no record source found, information from old Ren. #9, T32-6)

Drove railroad spike in root of 18" Fir tree.
Found both original witness trees but both badly rotted.
Marked the following new trees:
30" B.Oak S.42°41'W., 39.3 ft.
20" W.Oak S.52°15'W., 52.35 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Oct. 1967 - C.S. File 54/53-24

Found - Opened base of 27" D.Fir to find R.R. spike which is on North side of 27" D.Fir.
30" now 32" B.Oak S.42½°W., 39.3 ft., opened for scribe "T"
No trace of W.Oak, S.52°W. in SW nor in any other quad.
New BT - 18" D.Fir N.18°E., 9.5 ft. mkd. ¼ S28 CS BT.
This corner lies SW of fence corner running S & W about 15.0 ft.

Fd. OK, Jan. 1991, M 111-34

Raymond Wytcherley - For: Misty Morningstar - 7/2001 - C.S. File 65/38-3B - M 137-18

Found - Railroad spike in base of now 38" Fir stump.
All BTs are down. Trees have been clear cut to the South.
New bearing objects w/BT signs -
A steel fence post (measured to center of base) bears N.80°E., 3.63 ft.
A steel fence post bears S.80°W., 3.36 ft.
A W.Fir 9" dia., bears N.31°W., 31.6 ft. scribed "¼ S28 BT"
A Maple 12" dia., bears N.9°E., 70.1 ft. scribed "¼ S28 BT"

continued next page

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ray Wytcherly - For: Swanson Group Inc. - July 2006 - M151-31

Found - RR spike in base of now 38" fir stump all BTs are down. Trees have been clear cut to the south.

New bearing objects with BT signs:

A steel fence post (measured to center of base) bears N.80°E., 3.63 ft.

A steel fence post bears S.80°W., 3.36 ft.

A W.Fir 9" dia. bears N.31°W., 31.6 ft. scribed "¼ S28 BT"

A Maple 12" dia. bears N.9°E., 70.1 ft. scribed "¼ S28 BT"

Fd. RR spike & accessories by K. DeGroot, 10/2010 - M161-34
LAT: 42°45'14.92016"N LONG: 123°25'00.05738"W

Fd as per rec., not re-tied, A. DeGroot, 10/2016 - M171-19