

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8688)

Set a Fir post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S on W. face, from which
A Cedar 60" dia., bears N.50°E., 3 lks. dist., mkd. ¼ S BT.
A Laurel 10" dia., bears N.80°W., 23 lks. dist., mkd. ¼ S BT.

BLM resurvey by Rollin D. Aanrud, Cadastral Surveyor, under Group #616, surveyed June 1966/March 1967 (DCSO records Vol. 34 Page(s) 13993)

The ¼ sec. cor., monumented with a Cedar post 4 x 4 ins. sq., firmly set, protruding 24" above the ground, from which the original bearing trees:
The stump hole of a down Cedar, 24" dia., bears N.50°E., 3 lks. dist., no marks visible on tree.
The stump of a down Madrone 14" dia., bears N.80°W., 23 lks. dist., with illegible scribe marks visible in negative on overgrowth of the tree. (Rec. Laurel)
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S R 6 W
¼
S 9 | S 10
1966
from which new bearing trees
A Fir 6" dia., bears S.61°E., 46 lks., mkd. ¼ S10 BT.
A Cedar 8" dia., bears S.33°W., 36 lks., mkd. ¼ S9 BT.
Reset Cedar post alongside iron post.

Cor. Fd. and used in BLM resurvey by Dixon and Hartley, under Group #1337, surveyed July/Sept. 1989 (DCSO records, Vol. 48 page 18577)

Fd. OK by D. Edwards, Oct. 2003 - M143-23

DCSO-GIS Corner visitation - 2/19/2004 - Typed: 2/10/2011 - C.S. File 67/33-1

Monument - 2.5" IP/BC
Comment - ok