

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8679-80)

Set a Laurel post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S on N. face, from which
A Fir 24" dia., bears N.15°W., 22 lks. dist., mkd. 1/4 S BT
A Fir 22" dia., bears S.2°E., 46 lks. dist., mkd. 1/4 S BT.

Survey by Lorne V. Swearingen - For: Robert Dollar Co.- 1963
- C.S. File 51/255 and M 25-48

Set 5/8" Drill steel from 2 original BTs.

BLM resurvey by Rollin D. Aanrud, Cadastral Surveyor, under Group #616, surveyed June 1966/March 1967 (DCSO records Vol. 4 Page(s) 13991-92)

The 1/4 sec. cor., monumented with an iron rod, 1" dia., firmly set, protruding 6" above the ground, from which the original bearing trees:
A Fir snag 44" dia., bears N.15°W., 22 lks. dist., no marks visible on a bark blaze.
A Fir 44" dia., bears S.2°E., 46 lks. dist., with scribe marks 1/4 BT visible on a bark blaze.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S R 6 W
1/4 S 10
S 15
1966
from which new bearing trees:
A Fir 11" dia., bears N.3°E., 81 lks. dist., mkd. 1/4 S10 BT
A Fir 16" dia., bears S.88 1/2°E., 86 lks. dist., mkd. 1/4 S15 BT.
Reset iron rod alongside iron post.

Fd. OK, by L.Smith, April 27, 1983, M 94-19

Cor. Fd. and used in BLM resurvey by Dixon and Hartley, under Group #1337, surveyed July/Sept. 1989 (DCSO records, Vol. 48 Page 18565)