

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8681)

-----  
Set a Fir post 4 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S on N. face, from which  
A Fir 36" dia., bears S.25°W., 45 lks. dist., mkd. 1/4 S BT  
A Fir 40" dia., bears N.40°W., 12 lks. dist., mkd. 1/4 S BT

Douglas Co. Surveyors Office - James Byron, Deputy - S.A. Bilow, crew - June 4, 1959 - C.S. File 49/91-3

-----  
Found - Orig. 36" now 40" Fir snag, S.25°W., 29.7 ft., I open and find good scribing "BT".  
Now 48" Fir snag that checks bearing and distance for orig. NW BT, I open but do not find scribing, may have been bark scribed. This area burned, 1958.

Set Brass cap at cor. mkd: County Surveyors Office  
T 32 S R 6 W  
1/4 S 3  
S10  
1959

I find 3/4" iron rod bears N.45°E., 3.9 ft. from 1/4 cor.  
New BTs -32" R.Fir bears S.44°E., 33.6 ft. scribed 1/4 S10 CS BT.  
14" Cedar bears N.85°E., 71.3 ft. scribed 1/4 S3 CSBT

DCSO, J.Powell, Sept. 18, 1967, C.S. File 54/53-2 - "Trees cut, brass cap in place. No trees at all to scribe - tagged stumps-ribbon."

Fd. OK, L.D. Smith, April 27, 1983, M 94-19

Survey by Orrin K. Frederick - For: Boise Cascade Timberlands of Oregon - Feb. 21, 1985 - C.S. File 63/11 and M 90-67

-----  
Found - 1959 DCSO brass cap monument, firmly set, exposed 7" 40" Fir snag bears S.25°W., 29.7 ft. scribing visible.  
32" Fir stump bears S.44°E., 33.6 ft. 1/4 S visible.  
18" Cedar stump bears N.85°E., 71.3 ft. scribing visible.  
48" rotted Fir stump bears NW., no scribing visible.  
New BTs -7" Fir bears S.83°18'E., 2.80 ft. mkd. 1/4 S10 LS 1987 BT.  
7" Fir bears N.17°33'W., 20.33 ft. mkd. 1/4 S3 LS 1987 BT.

(Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Corner lies on gentle southerly slope approx. 150 ft. above Rd. #32-6-9.

BLM survey by Mark Dixon and Henry Hartley, Cadastral Surveyors, under Group #1337, surveyed July/Sept. 1989 (DCSO records Vol. 48 Page(s) 18580-81)

-----  
The ¼ sec. cor., perpetuated and recorded by Byron, 1959, further perpetuated and recorded by Frederick, 1985, monumented with an iron pipe 1¼" dia., firmly set, projecting 13" above ground with 1959 brass cap.

from which the remains of the original bearing trees

A burned Fir stump 44" dia., bears S.25°W., 45 lks. dist., with scribe marks BT visible on an open blaze.

A burned Fir stump 48" dia., bears N.45°W., 12 lks. dist., with old axe marks visible.

and the remains of the bearing trees mkd. by Bryon

A Cedar stump 20" dia., bears N.84°E., 107 lks. dist., with scribe marks ¼ S3 CS BT visible on a partially healed blaze.

A Fir stump 32" dia., bears S.44°E., 50 lks. dist., with scribe marks ¼ S BT visible on a partially healed blaze.

and bearing trees mkd. by Frederick

A Fir 10" dia., bears S.82°E., 4½ lks. dist., with scribe marks ¼ S10 LS 1987 BT visible on a partially healed blaze.

A Fir 9" dia., bears N.15½°W., 31 lks. dist., with scribe marks ¼ S3 LS 1987 BT visible on a partially healed blaze.

From this point, a point established by person(s) unknown, bears N.70°E., 0.05 chs. dist., monumented with an iron rod, 3/4" dia., firmly set, projecting 2" above ground.