

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3; & 34 of T31-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - George W. Hyde under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7948)

Set 1/4 sec. post on N. slope of Mt. from which
A Fir 30" dia., bears S.48°W., 34 lks. dist.
A Fir 30" dia., bears N.44°W., 25 lks. dist.

Survey by Ronald Quimby L.S. #1654 - For: Roseburg Lumber Co. March 1980 - M 79-25

Set a 5/8" Iron rod with alum. cap.
BTs - 12" D.Fir bears N.22°E., 8.0 ft. scribed 1/4 S34 BT.
10" D.Fir bears S.62°E., 19.7 ft. scribed 1/4 S3 BT.

BLM resurvey by Mark D. Dixon and Henry E. Hartley, under Group #1337, surveyed July/Sept. 1989 (DCSO records Vol. 48 Page(s) 18563-64)

The 1/4 sec. cor., reestablished by proportionate measurement and recorded by R. Quimby in 1980. There is no remaining evidence of the original corner, therefore this position is accepted as the corner; monumented with an iron rod, 5/8" dia., firmly set, projecting 5" above ground, with alum. cap mkd. 1/4 S34 S3 and a horizontal line, from which bearing trees mkd. by Quimby:

A Fir 15" dia., bears N.22°E., 12 lks. dist. with illegible scribe marks visible on a partially healed blaze.
A Fir 12" dia., bears S.60°E., 30 lks. dist. with illegible scribe marks on a partially healed blaze.

At the corner point

Set an stainless steel post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked T 31 S R 6 W

1/4 $\frac{S\ 34}{S\ 3}$
T 32 S
1986

Deposit the iron rod inside and a white "DEEP-1" magnetic marker at base of stainless steel post.

The corner is located on steep N. slope in timber.