

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8674)

-----  
Set a Laurel post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S. on W. face, from which  
A Fir 18" dia., bears S.70°E., 16 lks. dist., mkd. 1/4 S BT.  
A Fir 48" dia., bears N.10°W., 31 lks. dist., mkd. 1/4 S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S.A. Bilow, crew - June 9, 1959 - C.S. File 49/91-5

-----  
Found - Orig. 18" now 24" Fir, partly rotted snag, S.70°E., 18.6 ft., shows good scribing "1/4S".  
Orig. 48" now 50" Fir stump N.10°W., 20.5 ft. I do not find any scribing, may have been bark scribed.

Also find 3/4" Iron pipe at corner.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 32 S R 6 W  
1/4 S 10 | S11  
1959

New BTs -16" Cedar bears S.53°E., 38.0 ft. scribed 1/4 S11 CS BT.  
12" R.Fir bears S.85°W., 27.6 ft. scribed 1/4 S10 CS BT.

BLM resurvey by Rollin D. Aanrud, Cadastral Surveyor, under Group #616, surveyed June 1966/March 1967 (DCSO records Vol. 34 Page(s) 13986-87)

-----  
The 1/4 sec. cor., perpetuated and recorded by Byron in 1959, monumented with an iron pipe, 1" dia., firmly set, protruding 8" above ground, with brass cap, from which the original bearing trees  
A Fir snag 20" dia., bears S.70°E., 16 lks. dist., with scribe marks BT visible on opened blaze.  
A Fir snag 36" dia., bears N.10°W., 31 lks. dist., no marks visible.  
and bearing trees mkd. by Byron  
A Cedar 18" dia., bears S.52°E., 56 lks. dist., with a healed blaze.  
A Fir 16" dia., bears S.86°W., 41 lks. dist., with a healed blaze.  
Add the marks BLM 1966 to brass cap.

Fd. OK, by Lloyd Smith, April 27, 1983, M 94-19

(Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. OK, by O. Frederick, Feb. 1985, M 90-67

Cor. Fd. and used in BLM survey by Dixon and Hartley, under Group #1337, surveyed, July/Sept. 1989 (DCSO records, Vol. 48 Page 18571)

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #2125, surveyed July/Nov. 2005 - (DCSO records Vol. 55 Page(s) 21467-8)

-----  
The ¼ sec. cor. of secs. 10 and 11, monumented with an iron post, 1½" dia., firmly set, projecting 15" above the ground, with brass cap mkd. COUNTY SURVEYORS OFFICE  
BLM  
1/4 S | S  
10 | 11  
T 32 S R 6 W  
1966  
1959

from which the remains of the original bearing trees reported by Dixon and Hartley  
A broken off fir stump, size indeterminate, bears S.70°E., 10.6 ft., with scribe marks BT visible on detached blaze.  
A sawed fir stump, 48" dia., bears N.10°W., 22.4 ft., no marks visible.  
and the remains of bearing trees mkd. by the Douglas County Surveyor's Office, reported by Dixon and Hartley  
A cedar, 20" dia., bears S.54°E., 37.0 ft., with illegible scribe marks visible on a partially healed double blaze. (Record, 37.6 ft.)  
A sawed fir stump, 15" dia., bears S.83¾°W., 27.1 ft., with a healed double blaze. (Record, S.85°W., 27.7 ft.)  
and a new bearing tree  
A madrone, 17" dia. bears S.64¾°W., 19.1 ft. mkd. ¼ S10 BT